



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
377	Men's Kite	SLO	Wings	8 AUG 2024 18:18	We kindly ask for the substitution of the wing because they got damaged during rescque. Front wing No. 10615622 Back wing No. 10623972	Yes	TC inspected the glider and the damage was genuine. Replacement was presented to the TC approved. New Serial No. Frontwing:10573951, Stabiliser: 10594744
376	Men's Kite	SLO	Substitution of the kite	8 AUG 2024 18:15	We kindly request the substitution of the kite 23 m2 id number 2C23SLO042416943, ripped.	Yes	TC inspected the kite and the damage was genuine. Replacement to the pre-registered spare (same brand, model, and size) approved. New serial number: 2C23SLO-0924-17110
375	Mixed Multihull	SWE	Gennaker	7 AUG 2024 17:16	We need to make a repair to the gennaker clew because of a 5cm tear approximately 25 cm from the clew point.	Yes	Repair has been inspected and is genuine. Repair is approved. TC does not need to re inspect
374	Men's Kite	FRA	23m kite VMG	7 AUG 2024 19:06	I noticed a hole 5cm wide on my kite near the trailing edge because of a tangle. Have to put a patch on it.	Yes	07/08/2024 - 19:07 : Equipment inspected, damage genuine repair permitted Please Present Repair to the TC before moving Equipment into the Pitlane on 08/08/2024
373	Women's Dinghy	BEL	Hull	6 AUG 2024 21:29	Request for the supplier to clean the hull with acetone after the tow + request to wash & clean the hull with water & soap tomorrow in quarantine area.	No	
372	Mixed Multihull	NZL	Cunningham System	6 AUG 2024 17:49	Permisi3n to replace Cunningham rope system as it has broken	Yes	Request approved. TC does not need to inspect after completion.
371	Mixed Multihull	NED	cunningham control line	6 AUG 2024 17:37	To re-splice the cunningham control line for the Medal Race.	Yes	Request approved. TC does not need to inspect after completion.
370	Mixed Multihull	NZL	Rudder	6 AUG 2024 17:35	Request to fill the bolts of both Port and Starboard rudders, as the filling has popped out.	Yes	Request approved. TC does not need to inspect after completion.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
369	Women's Kite	GER	21m Kite black pulley lines	7 AUG 2024 11:46	I'd like permission to replace the black pulley line on the 21m kite due to excessive shrinkage following the kite landing in the water	Yes	06/08/24: TC inspected the Kite. Damage is genuine. Repair approved. Equipment to be presented to the TC for re-inspection prior to the first warning signal on 7 August 2024 07/08/2024: Repair inspected by TC, repair approved
368	Men's Kite	AUT	Kite 23m2	6 AUG 2024 16:11	I request to repair the kite 23m2 K-04934, equipment control # 128, as there are some small holes on both sides of the kite at the trailing edge.	Yes	06/08/2024: Equipment inspected by TC repair approved. Repaired Kite inspected
367	Men's Kite	AUT	Kite 23m2	6 AUG 2024 15:29	I request to exchange 2 bridles on my 23m2 kite due to damage	Yes	06/08/24: TC inspected the Kite. Damage is genuine. Repair approved. Needs to be presented to the TC for re-inspection prior to the first warning signal on 7 August 2024 update 18:21 : TC inspected repair, repair approved
366	Women's Kite	AUS	Bridal line BM4	7 AUG 2024 11:50	The bridal line (BM4) was accidentally caught in the zipper of the kite bag and we have noticed slight damage to the bridal line (BM4). We request permission to replace the bridal line (BM4).	No	06/08/2024: Equipment Inspected, repair of Bridle (BM4) at VMG15 inside the boat park approved. Please present the Equipment to the Technical Committee before the next scheduled Race on 06/08/24 18:26 : Equipment inspected, repair of Bridle (BM3) inside the boat park approved, please present Equipment to the TC again, before the first warning Signal of 07/08/2024 07/08/2024 Repair not successful, damaged bridle will be used.
365	Men's Kite	BRA	23m2 kite	6 AUG 2024 12:47	There is 3cm tear on the front edge of my Kite (serial 2c23-BRA -2024-18801 and Paris 2024 number 26 sticker) . I request to use tape to repair it.	Yes	06/08/24: TC inspected the Kite. Damage is genuine. Repair approved. Needs to be presented to the TC for re-inspection prior to the first warning signal on 6 August 2024 Update 06/08/24-12:46 : Repair inspected and approved



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
364	Women's Dinghy	SUI	ILCA6 - Hull	6 AUG 2024 11:11	We are requesting the permission to clean a black line on starboard side of the hull. Verbal request was already done to the TC in quarantine area	Yes	Approved to be cleaned by the supplier
363	Men's Kite	USA	L kite men 23m vmg2	6 AUG 2024 11:54	Our I size kite has a small tear on the right wingtip on the leading edge. We are requesting to repair this tear with the provided tape from the manufacturer. 23m vmg2 Sn, 2023-0723-99681 K-05880	Yes	06/08/24: TC inspected the Kite. Damage is genuine. Repair approved. Needs to be presented to the TC for re-inspection prior to flag D on 6 August 2024 update: Kite inspected after repair, repair approved.
362	Women's Dinghy	BEL	Cleaning	6 AUG 2024 9:32	Request to clean and wash the boat with soap in the quarantine area	Yes	Permission granted for washing of boat in accordance to ER 7.3.5 in the quarantine area subject to supervision by the TC
361	Mixed Multihull	ARG	Mainsail strap	6 AUG 2024 9:06	Hi, I would like to request the permission to repair the strap of our mainsail. It is close to breaking, we will add stitches and a safety rope	Yes	no need to re-inspection
360	Men's Dinghy	POR	Center board stoper	5 AUG 2024 18:54	Need to change center board stopper on the water today	Yes	
359	Men's Dinghy	IRL	Hull	5 AUG 2024 18:46	Clean the port side from black marks	Yes	Approved to be cleaned by the supplier
358	Men's Dinghy	NZL	Hull	5 AUG 2024 18:36	Request to fix the rubber protection on the center case of the supplied hull	Yes	To be fixed by the supplier
357	Men's Dinghy	AUS	Bailer	5 AUG 2024 18:28	Request to check bailer as trailing edge is not sitting flush.	Yes	To be fixed by the supplier
356	Women's Dinghy	BEL	Hull	5 AUG 2024 18:05	Request to supplier to use acetone to clean the side of the hull	Yes	Approved to be cleaned by the supplier
355	Women's Dinghy	USA	ILCA hull	5 AUG 2024 17:58	Can the supplier please acetone the starboard and port side top gunnel of my hull to clean from side towing	Yes	Approved to be cleaned by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
354	Mixed Multihull	USA	Replace traveler cleat	5 AUG 2024 17:16	One of the springs on a lobe of the traveler cleat broke. Before the first race we radioed the race committee to notify the cleat needed to be replaced. The measurers were called over to our boat and granted permission to replace the cleat. Once we replaced the cleat the measurer inspected the cleat.	Yes	TC inspected on the water and approved. No further inspection required.
353	Mixed Multihull	NZL	Rudder	5 AUG 2024 16:56	Request to fill the bolts of both Port and Starboard rudders, as the filling has popped out.	Yes	TC approved this change on the water. No inspection needed
352	Mixed Multihull	NED	spring of mainsheet cleat	5 AUG 2024 16:54	To permanently replace the spring for the mainsheet cleat. The spring has already been replaced on the water today, between races 7 and 8, after oral approval by the TC (Alistair)	Yes	TC approved this change on the water. No inspection needed
351	Men's Kite	POL	Permission to re-fill the gap between the mast and the fuselage	5 AUG 2024 16:02	I kindly ask the permission to re-fill the gap between mast and fuselage with a silicone as permitted in CR 8.3(d). After I filled the gap that was approved today, the front of the filler fell off and needs to be re-filled.	Yes	Inspected by the TC and approved. It needs to be presented to the TC before for re-inspection
350	Men's Kite	NZL	Foil Fuselage	5 AUG 2024 12:17	Request to Sand the Foil Fuselage	Yes	TC inspected and approved.
349	Men's Kite	MRI	Kite 23m VMG 2 - 95252	5 AUG 2024 10:59	Request to repair leading edge and bridles	Yes	TC inspected the Kite. Damage is genuine. Repair approved. Needs to be presented to the TC for re-inspection. TC inspected the repair and it is approved.
348	Women's Dinghy	FIN	Sail	5 AUG 2024 10:44	Requesting to put sail tape over a small hole in the sail	Yes	Approved for repair by the supplier
347	Men's Kite	POL	Permission to fill the gap between mast and fuselage	4 AUG 2024 20:08	I kindly ask the permission to fill the gap between mast and fuselage with a silicone as permitted in CR 8.3(d).	Yes	Action in accordance with class rules C.8.3.(d) in the boat park approved. Please present equipment to TC before the first warning day on 05/08/24
346	Men's Kite	POL	Permission to cover the screws	4 AUG 2024 20:06	I kindly ask for permission to cover the screws in fuselage with the filler.	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO before the first warning day on 05/08/24



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
345	Mixed Multihull	SWE	Mainsheet	4 AUG 2024 19:27	The cover in the mainsheet splice has started to come undone and we would like to resplice it to avoid further issues.	Yes	TC does not need to inspect. Approval to repair is approved. TC to inspect before next race. UPDATE 1030 05/08/2024 TC has inspected repair and approved.
344	Women's Kite	SUI	Kite foil woman - SUI sail 23	4 AUG 2024 19:27	We ask the permission to repair our 23sq sails damaged in the incidend on 2nd downwind in race 4. TC on the beach took pics	Yes	Equipment Inspected, repair of VMG23 #98344 inside the boat park approved. Please present the Equipment to the Technical Committee before the next scheduled Race on 05/08/24
343	Mixed Multihull	NZL	Camera Mount	4 AUG 2024 19:14	Request to Replace Camera Mount. Broken on Race one of day	Yes	
342	Mixed Multihull	NZL	Port Hull	4 AUG 2024 19:14	Request to repair a chip on port hull Bow	Yes	Permission to make repair to port hull at bow is approved. TC to inspect before next race. UPDATE 1030 05/08/2024 TC has inspected repair and approved.
341	Mixed Multihull	GER	Starboard rudder elevator and rudder foil	4 AUG 2024 19:11	We would like permission to repair our damaged starboard rudder elevator and rudder foil. We'd like to take it to the container for repair.	Yes	TC has inspected the damage and it is genuine. Permission to remove stb rudder to container park for repairs is approved. STB Rudder serial number. 00674 Permission to remove form can be collected from the race office. TC to inspect repair before next race. UPDATE 1030 05/08/2024 TC has inspected repair and approved.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
340	Men's Kite	FRA	Chubanga Kitefoil	4 AUG 2024 19:08	My screw holes on my glider who make connection to the mast has been filled in and confirmed by equipment inspection guy yesterday. But after day 1, the finition went out and I have to do it again.	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between before the first race at 05/08/2024 in the boat park.
339	Men's Kite	FRA	23m Flysurfer Kite	4 AUG 2024 19:03	Because of a contact with someone else, I have to repair my kite tip on leading edge.	Yes	Equipment Inspected, repair of VMG23 #16273 inside the boat park approved. Please present the Equipment to the Technical Committee before the next scheduled Race on 05/08/24
338	Mixed Multihull	GER	New bungee for trapeze wire	4 AUG 2024 19:02	Replace broken bungee trapeze wire	Yes	Approval granted to replace trapeze bungee. TC to inspect after new bungee fitted. UPDATE 1030 05/08/2024 TC has inspected repair and approved.
337	Men's Kite	BRA	Foils	4 AUG 2024 19:02	We kindly request to sand our foils (routine maintenance allowed by CR C 8.3b and ER 1.4.6).	Yes	Maintenance, as defined in the ERS, may be performed provided it complies with the applicable class rules. Also see RFI 160
336	Women's Kite	NZL	Foil Fuselage, front Wing, Mast	4 AUG 2024 18:58	Request to Repair due to damage	Yes	Foil System inspected. Maintenance, as defined in the ERS, may be performed provided it complies with the applicable class rules. Also see RFI 160
335	Women's Dinghy	BEL	Centreboard back friction pad	4 AUG 2024 18:09	Request to change the centreboard back friction pad. It's cut in half.	Yes	Approved for replacement by supplier
334	Men's Dinghy	DEN	Hiking strap bolts	4 AUG 2024 16:48	I would like to request having my hiking strap bolts tightened	Yes	Approved to be fixed by the supplier
333	Men's Dinghy	GBR	Cotpit bung	4 AUG 2024 16:38	I would like a new cotpit bung after I lost mine yesterday sailing (retrospective request) from the boat supplier. Thanks	Yes	Approved to be replaced by the supplier
332	Mixed Dinghy	FRA	Centerboard	4 AUG 2024 15:14	I request to do some small repair on the trailing edge of my centerboard on the boat park	Yes	TC inspected and accepted. repair must be done in the boat park allocated area.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
331	Mixed Dinghy	ESP	Hull astern flap window	4 AUG 2024 15:02	We kindly request for permission to repair the flap at the astern of our hull. (Bailer window flap) Thanks	Yes	Accepted. Repair must be done in the boat park allocated area.
330	Mixed Dinghy	AUT	Gasket protection tape.	4 AUG 2024 14:29	I kindly request to renew the gasket protection tape.	Yes	Gasket tape renewal in the boat park allocated area is accepted.
329	Men's Dinghy	ESA	Change front frictions tape	4 AUG 2024 11:07	Hi I need the front friction tape replaced the one I had broke	Yes	Approved for replacement by the supplier
328	Men's Dinghy	HKG	Rubber pad at the front of the centerboard case	4 AUG 2024 9:39	I would like to replace the rubber pad at the front of my centerboard case as the previous one fell off yesterday during racing.	Yes	Approve for replacement by supplier
327	Mixed Multihull	ESP	Mainsail stickers	3 AUG 2024 21:19	After racing today, we figured we were missing some event stickers on the mainsail comparing to other teams. We are missing Paris 2024. We wait for your instructions to follow. Thanks in advance .	Yes	Please bring the sail on 04 August at 10.00 am to the Grapefruit office
326	Mixed Multihull	NED	port rudder elevator	3 AUG 2024 18:37	To repair the port rudder replacement elevator	Yes	Tc has inspected and damage is genuine. Approval to repair. TC to inspect repair before next race. UPDATE 1430 04/08/2024 TC have inspected and approved.
325	Mixed Multihull	NED	Starboard rudderblade	3 AUG 2024 18:32	To repair the starboard rudderblade (small repair trailing edge). after damaging the rudder in R2 at the start (DNF)	Yes	TC has inspected and damage genuine. Approval to repair. TC to inspect before next race. UPDATE 1430 04/08/2024 TC have inspected and approved.
324	Men's Kite	ANT	Filling in screw holes on the glider.	3 AUG 2024 19:16	Can I fill in the screw holes on my glider with putty and sand it.	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO before Flag D is displayed at 04/08/2024



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
323	Mixed Dinghy	GER	Vang system	3 AUG 2024 18:19	Request to change the bolt in the vang line to boom attachment. We would like to increase the size of the bolt to prevent it from pulling through the existing hole in the boom.	Yes	Modification of bolt size inside the boom to provide better anchorage is accepted. No further inspection required.
322	Women's Kite	ITA	Event sticker of the mast	3 AUG 2024 18:02	I request to get a new event limitation sticker for my mast as the one I have is falling off	Yes	Approved to replace the event limitation mark
321	Mixed Multihull	AUS	Camera mount	3 AUG 2024 17:51	Request camera mount to be repaired because the attachments have failed.	Yes	
320	Mixed Multihull	GER	Tiller Extension	3 AUG 2024 17:50	Broken tiller extension replaced after Race 1 with approval of the TC on the water	Yes	TC inspected and damage is genuine. Replacement approved.
319	Mixed Multihull	CHN	Reset the camera shelf	3 AUG 2024 17:44	Hi Hi Technical committee, I am from China, Nacra 17 sailor , we need to reset the camera shelf.many thanks.	Yes	
318	Mixed Multihull	CHN	Rudder clamp	3 AUG 2024 17:40	Hi Hi Technical committee, I am from China, Nacra 17 sailor , we broken the starboard's rudder clamp , and we need to change new one .many thanks.	Yes	TC inspected and damage is genuine. Replacement approved. Present the new one to the TC before the next race. UPDATE 1430 04/08/2024 TC have inspected and approved.
317	Mixed Multihull	SWE	Trapeze bungy, Cunningham take up, righting line. Reglue nonskid on port and starboard hulls.	3 AUG 2024 17:40	Due to a crash resulting in the crew flying out of position a number of items need to be repaired or swapped. The original, soft nonskid has come undone in two places and need to be reglued.	Yes	TC inspected and the damage is genuine. Repair is approved no need to be re-inspected
316	Women's Kite	USA	Hydrofoil Glider	3 AUG 2024 17:37	Foil was tangled on anchor line during training. Slight damage on stabilizer. Requesting permission to apply epoxy and sand	Yes	03/08/24: Please present Equipment prior to repair to the TC no later than 04 August 24 10:00 update: Equipment inspected, action approved and inspected after repair



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposonse
315	Mixed Multihull	USA	Obs camera mount	3 AUG 2024 17:37	In the first race, camera mount became disconnected from the pole, but remained attached by a cable tie on the pole support wire. After the race, we notified the measure and he requested to have us put the Cam mount in the trampoline pocket for the remainder of the day we did as he requested. Once we came, assure someone working for the OBS came by and retrieved the camera out from our boat. We requested that OBS comes and remount the camera out to our pole	Yes
314	Mixed Multihull	NED	port rudder blade and elevator	3 AUG 2024 17:36	To replace the port rudder blade and elevator , which got damaged at the start of Race 2 (DNF)	Yes TC inspected and damage is genuine. Replace is approved. To be presented to the TC before the next race. UPDATE Replacement rudder inspected and approved. Old serial number 759 Replaced by 579
313	Women's Kite	POL	Request to replace spare kite	3 AUG 2024 17:33	I have three holes in my spare kite size 21 and I kindly ask to replace my spare kite to another kite of the same brand (VMG 2) and size (21). The number of the new kite for replacement is 2C21POL-1224-17379	Yes Spare kite inspected by TC, replacement approved.
312	Women's Kite	AUS	Foil mast	3 AUG 2024 17:19	Request replacement for damaged event limitation marking (sticker) on foil mast.	Yes Approved to replace the event limitation mark
311	Mixed Multihull	NZL	Camera Mount	3 AUG 2024 17:12	Camera Mount got damage due to wave state. Request to repair / Replace by organization.	Yes
310	Women's Dinghy	URU	Vang main line	3 AUG 2024 17:02	My vang main line is about to tear, i request permission to change the rope for a new one.	Yes Approved to be changed.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
309	Women's Kite	POL	Replacement of Look of the Games logo	3 AUG 2024 16:55	Today during training Look of the Games logo started falling off my board and got destroyed. I kindly ask the permission to replace the current sticker with the new one.	Yes	approved to replace the event limitation mark
308	Men's Kite	USA	Mast Event Sticker	3 AUG 2024 16:52	Mast event sticker is starting to fall off and needs replacement	Yes	Approved to replace the event limitation mark
307	Women's Dinghy	POL	Permission to repair the vang	3 AUG 2024 16:51	I kindly ask for permission to repair my vang that I had to replace on the water today due to the broken rope. I would like to repair the original vang.	Yes	TC inspected the vang. The damage is genuine. Approved to be repair. To be presented to the TC before the first race of the 04 August 2024.
306	Women's Dinghy	POL	Vang	3 AUG 2024 16:50	Today on the water I had to replace my vang due to the broken line. My coach notified TC on the water before I raced again as required by ER 3.1. I ask for official approval for the replacement I made.	Yes	Vang was inspected on the water by the TC and replace on the water was approved.
305	Women's Dinghy	FRA	Cunningham and hull	3 AUG 2024 16:44	I broke my ropes of the Cunningham. I ask to change it. And about hull, my port side hull is damage. Please come to see and repair. Thanks	Yes	Approved to change the ropes. Please present the boat to be repair by the supplier,
304	Men's Kite	SGP	Registered Levitaz V1 Mast (Serial Nr: 10615680)	3 AUG 2024 16:43	Slight damage to the lower leading edge of the mast. Request to apply filler coating and sand it down to profile after application.	Yes	Mast inspected by the TC. Damage genuine. Repair approved in accordance with the CR. To be presented to the TC before the first race.
303	Women's Dinghy	SUI	Hicking strap	3 AUG 2024 16:40	Replacement of the straps as it's steached and always twisted. I request to change with my personal	Yes	approved to be replaced with her own, which shall be fitted by the supplier
302	Men's Kite	ISR	Foil and board	3 AUG 2024 16:07	My board and foil stickers fall to the water. I'm requesting to get new ones.	Yes	Approved to replace the event limitation mark
301	Men's Dinghy	GBR	Friction pad	3 AUG 2024 16:02	To replace the friction pad as it has cracked slightly on the middle, please. Thanks	Yes	approved to be replaced by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
300	Men's Dinghy	ITA	Boat hull bow	3 AUG 2024 15:46	As my boat capsized on the trolley rigging up the bow of my boat was damaged... please can the boat supplier mend it this evening?	Yes	Damage reviewed and approve for repair by the supplier Approve for athlete to bring the boat and equipment to the supplier hanger for the repair.
299	Men's Dinghy	ITA	Rudder	3 AUG 2024 15:45	Many thanks I had a problem before sailing... the boat capsized was j the trolley as I was rigging with a strong gust.... My rudder fell of the boat and was damaged... I was able to change the rudder by switching it before going on both he water.	Yes	TC reviewed the damage and approved for athlete to race with the spare rudder provided by the supplier for Races 5 & 6 TC approve for supplier to repair the damaged rudder and athlete will revert to this rudder that is originally issued to him for subsequent races
298	Men's Kite	NZL	Kite bolt fairing	3 AUG 2024 13:07	Thank you Requesting permission to fill, fair, and sand glider bolt heads after assembling equipment post measurement as permitted in class rule C8.3(c)	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to TC between 17:00 an 19:00 at 03/08/2024 in the boat park.
297	Women's Kite	NZL	Kite bolt heads	3 AUG 2024 13:05	Requesting permission to fill, fair, and sand glider bolt heads after assembling equipment post measurement as permitted in class rule C8.3(c)	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to TC between 17:00 an 19:00 at 03/08/2024 in the boat park.
296	Mixed Multihull	GER	Foils	3 AUG 2024 12:17	Upon returning to my boat this morning I found blistering on the surface of the foils caused by the heat in the boat park. I'd like permission to maintain and/or repair the foils as necessary	Yes	1230 -3/08/2024 Foils inspected by TC ZS 00739 ZP 00750 Maintenance is permitted by class rules No further inspection needed.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
295	Mixed Dinghy	SWE	Gaskets protection tape	3 AUG 2024 11:00	Hi, If the thin protective tape on the gaskets is warn out or unglued a bit, are we allowed to replace the tape? It is a regular maintenance job, happens sometimes in 470 that this tape gets damaged or unglued. Thanks, SWE 470, 03.08.2024 10:50	Yes	It is approved to replace the white tape over the starboard gasket at the forward end. No further inspection is required.
294	Men's Windsurfing	GBR	Fuselage SC 502413	3 AUG 2024 9:35	Fuse QR code replacement please	Not decided	
293	Women's Kite	ITA	FOIL SYSTEM	3 AUG 2024 9:25	I kindly ask for the permission to fill and fair holes of the screws of mast and fuselage connections and gaps between components of the foils system as per CR C.8.3 (b), (c), (d). If approved, can I please carry the above described mantainance/repairs in the Container Park? Thanks for your attention	No	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to TC between 17:00 an 19:00 at 03/08/2024 in the boat park.
292	Men's Kite	ITA	FOIL SYSTEM	3 AUG 2024 9:24	I kindly ask for the permission to fill and fair holes of the screws of mast and fuselage connections and gaps between components of the foils system as per CR C.8.3 (b), (c), (d). If approved, can I please carry the above described mantainance/repairs in the Container Park? Thanks for your attention	No	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.
291	Men's Kite	USA	Glider	2 AUG 2024 18:55	Requesting permission to fill, fair, and sand glider bolt heads after assembling equipment post measurement	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
290	Women's Dinghy	AUS	Ratchet block	2 AUG 2024 16:27	Request ratchet block replacement as it is making strange noises and jamming under load.	Yes	Approved for replacement
289	Women's Dinghy	SLO	Rudder blade	2 AUG 2024 16:24	I am kindly asking to get my rudder blade repaired. During washing my boat I discovered a dent on the lower part of the rudder blade. Please inform me where to bring the blade for reparation. Kind regards.	Yes	Approve for repair by supplier Sailor can bring the rudder to the supplier's hanger for repair it is not required to re-present the rudder for inspection
288	Men's Dinghy	GUA	Front Cente board pad	2 AUG 2024 16:23	The front pad of the centerboard was replaced yesterday but it was replaced by a different pad that is thinner and is causing the centreboard to rise up when not required. Please can it be replaced by the same one as the original pad and the same one that all the other ILCA 7's have. Thanks	No	Please see item 287
287	Men's Dinghy	GUA	Centerboard	2 AUG 2024 16:08	There is glue from the front centerboard friction pad on the top of the centreboard. Please can this be removed. Thanks	Yes	Approved for fixing by supplier together with request 288
286	Mixed Dinghy	USA	Rudder	2 AUG 2024 14:58	I am requesting permission to make a small repair to my rudder. Thank you	Yes	Please present your rudder at 10:30 on the boat park for inspection. Update: 03/08/2024 10:50 It is approved to carry on repair. No further inspection is required after the repair.
285	Women's Kite	CAN	Glider	2 AUG 2024 14:51	Request to repair crack to stabilizer wing tip in the container park, and also a small ding on the trailing edge of the front wing. Class measurer (Henrik) has seen the damage.	Yes	Glider with the Serial No. C05304 has been inspected. Repair outside the boat park approved. For leaving the boat park with your Equipment please use permission form available in the race office.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
284	Men's Kite	GBR	Foil Glider	2 AUG 2024 13:41	As per class rules I would like to fill the screw holes on the fuselage and joint connection of fuselage to mast, according to C8.3 (C&D) spoken to ITO who has agreed this is legal but adviced I put a submission in	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.
283	Women's Kite	AUT	Foiling system	2 AUG 2024 13:24	I request that the screw holes in the foiling system and the gaps between the different components may be filled and faired in accordance with class rules C.8.3.(c) and C.8.3.(d).	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.
282	Men's Kite	AUT	Foiling system	2 AUG 2024 13:23	I request that the screw holes in the foiling system and the gaps between the different components may be filled and faired in accordance with class rules C.8.3.(c) and C.8.3.(d).	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present Equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.
281	Women's Kite	USA	Hydrofoil	2 AUG 2024 12:53	Requesting permission to fair over the fastener heads on the bottom of the Glider of our registered Hydrofoil.	Yes	Action in accordance with class rules C.8.3.(c) and C.8.3.(d) in the boat park approved. Please present equipment to ITO between 17:00 an 19:00 at 03/08/2024 in the boat park.
280	Mixed Multihull	TUR	Front bridle damaged	2 AUG 2024 11:37	Our front bridle is damaged. We kindly request permission to change it	Yes	02/08/24: TC to inspect damage. 02/08/24-update: Bridle stb side is damaged. Permission to replace is granted. New bridle to be inspected .by 1000hrs 03/08/24 03/08/2024 Bridle inspected and approved by TC
279	Women's Dinghy	PER	centerboard friction pads	2 AUG 2024 11:08	I would like to replace the centerboard friction pad because its already worn out.	Yes	Approved for replacement by supplier
278	Men's Dinghy	PER	Mainsheet	2 AUG 2024 11:05	Request to change mainsheet. Changing it due to too much wear. Changing it for the same model and width.	Yes	Replacement aproved
277	Men's Dinghy	THA	Centerboard stopper grip	2 AUG 2024 10:57	It came off and need a new one please	Yes	Approved for replacement by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
276	Men's Dinghy	BRA	centerboard case front rubber	2 AUG 2024 10:52	I need to fix/replace my centerboard case black rubber.	Yes	Approved for replacement by supplier
275	Mixed Dinghy	POR	CHANGE PLACE AT BOAT PARK	2 AUG 2024 10:47	Due to the strong wind forecast for today at the end of the day and tomorrow, we requested authorization to place our boat 470 - POR, today the 2nd and tomorrow the 3rd of August, in place of the 49 er FX POL, since in our place there is no possibility of securing the boat to the ground.	No	Please raise your request to organizer in RFI system.
274	Women's Dinghy	CYP	Rubber piece in front of daggerboard	2 AUG 2024 10:38	The rubber piece I'm front of the daggerboard is coming out and a bit destroyed. Is it possible to replace it? Thank you	Yes	Approve for replacement by the supplier
273	Men's Windsurfing	GBR	SC441331 front wing	2 AUG 2024 10:25	QR code replacement please	Not decided	
272	Women's Skiff	FRA	Mainsheet	2 AUG 2024 10:13	Could we do Small maintenance on the main sheet in the pitlane	Not decided	
271	Women's Dinghy	BER	Tracker mount	2 AUG 2024 10:03	there is some damage to my tracker mount and the one side is missing to safely attach tracker to. I would like to request a new mount to be attached so that I can securely attach tracker	Not decided	
270	Men's Skiff	CRO	Port wing repair	1 AUG 2024 19:58	Request for port wing repair with epoxy	Yes	Damage inspected and approved for repair. To be re-inspected in quarantine area before boat is moved to the pit lane on 02/08/2024
269	Women's Dinghy	ROU	rubber piece at the front of the daggerboard case	1 AUG 2024 18:36	Hi! My rubber piece at the front of the daggerboard case has started coming off to the point that there is almost none left. I request to put a new piece please. (It's the small grey one 3cm) Thank you	Yes	approved for replacement by the supplier.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
268	Men's Skiff	IRL	49er Wing non slip tape	1 AUG 2024 18:13	Hi , I am using this form after discussing with Rob . We want to replace a small amount of non slip tape on the front of both wings as its damaged and no longer will be effective.	Yes	01/08/2024 - the boat has been inspected.; The replacement of a small amount of non slip tape on the front of both wings after opening of the quarantine area on 2 August 2024 is accepted
267	Men's Dinghy	ARG	hiking strap	1 AUG 2024 17:06	I need to change the hiking strap provided from supplier because is twisting when i am hiking. i would like to change it for one mine please	Yes	Replacement of hiking strap to sailor's own is approved. The supplier will install it in the boat park.
266	Men's Dinghy	GUA	Centerboard case front friction pad	1 AUG 2024 17:04	The foam pad on the front of the ILCA 7 GUA hull has fallen off. Please can the equipment suppliers replace it. Many thanks	Yes	Approve for repair of centreboard case front foam pad by the supplier
265	Men's Dinghy	SLO	Rudder blade	1 AUG 2024 16:57	I am kindly asking to get my rudder blade repaired. After the collision on the starting line, the blade gets a dent on the aft part. Please inform me where to bring the blade for reparation. Kind regards.	Yes	Damage is reviewed Approved for repair by the supplier Sailor permitted to bring the rudder blade to the supplier hanger for repair. it is not required to re-present for inspection after repair
264	Men's Dinghy	CRO	Bailer	1 AUG 2024 16:54	Bailer is not working properly. Kindly ask replacement. Thank you	No	Replacement rejected Approve for repair of bailer by the supplier in the boat park
263	Men's Dinghy	CYP	Bailer	1 AUG 2024 16:51	Kindly ask replacement of bailer that I blocking water escaping from the boat.	Yes	Approved for replacement by the supplier in the boat park
262	Men's Dinghy	AUS	Centerboard anti-wear tape	1 AUG 2024 16:42	Request replacement centerboard anti-wear tape (at front of centerboard case), which has fallen off.	Yes	Approved for replacement by the supplier
261	Women's Windsurfing	FRA	Change of front wing	1 AUG 2024 11:53	I request to change my foil Wing called "Use" and take the "spare" one for racing if the repair made by supplier is not suitable.	Not decided	
260	Women's Windsurfing	FRA	Foil mast Use Fra Women	1 AUG 2024 11:52	I request to change my foil mast called "Use" and take the "spare" one for racing if the repair made by supplier is not suitable.	Not decided	



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
259	Men's Dinghy	DEN	Hiking strap	1 AUG 2024 11:40	I would like to rrqueat a change of hiking strap as the condition is questionable	Yes	Damage reviewed Approved for replacement by Supplier
258	Men's Windsurfing	NED	hole in nose of board (see request 165)	1 AUG 2024 11:35	After approval (request 165) the hole in the nose of my board was repaired. The repair has come off, so it needs to be fixed once more.	Not decided	
257	Women's Windsurfing	ESP	Sail	1 AUG 2024 11:27	The batten n4 pocket has a tear, and to prevent a bigger breakage I request a repair, if some tape can be applied.	Not decided	
256	Men's Windsurfing	ESP	Screw at the tail end of the boom	1 AUG 2024 11:17	The screw is not holding the pulley, so we request to get it fixed	Not decided	
255	Men's Dinghy	FIJ	Center case front protector	1 AUG 2024 11:13	Please replace.	Yes	Replacement approved by supplier
254	Men's Dinghy	FRA	Sail sticker	1 AUG 2024 11:09	My striker with my name in the sail is not placed at the same position than the other. I ask to be change. Jb	Not decided	
253	Men's Skiff	CRO	Vang rope	1 AUG 2024 11:04	Request to change damaged vang rope.	Yes	01/08/2024: The equipment has been inspected. Change of damaged vang rope.approved
252	Women's Windsurfing	NED	Washer replacement	1 AUG 2024 10:15	The washer has been bent a bit because of the pressure on the foil box. Request to replace washers	Not decided	
251	Women's Windsurfing	NED	Board QR code and Serialnr	1 AUG 2024 10:05	Board QR code SC 012 423 Board serial nr ST24 IQF0 C95B 24010050	Not decided	
250	Women's Windsurfing	NED	Board	1 AUG 2024 10:04	Request for replacement of board - broken foilbox	Not decided	



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
249	Men's Skiff	NED	49er gennaker	31 JUL 2024 21:35	We ripped our kite today in race 12, tomorrow in the medal race we would like to substitute our ripped kite with the kite that is in the TC rib. We are currently in 11th position overall, but the result of an ongoing protest against China could put us 10th overall, thats why this request is made at this time.	Yes	TC inspected damaged gennaker. Use of the spare gennaker is approved. NED to provide new spare gennaker to TC before release for the Medal Race
248	Men's Skiff	NED	post-race inspection for Medal Race Men's Skiff	31 JUL 2024 21:24	We finished 11th overall, but CHN is being protested by the TC. Depending on the outcome of that protest, we might become 10th. We want to comply with ER 4.11, which has no cut-off time, but everyone is gone. We would want to comply with ER 5.2 as well: to be in Quarantine area within 2 hours after the end of protest time. PTL was 19.37, so Quarantine deadline is 21.37. There is no one there. We are trying to find the TC in Building 1 now, but wanted to submit this before 21.37.	Not decided	
247	Men's Windsurfing	GBR	SC441331 front wing	31 JUL 2024 21:17	QR CODE REPLACEMENT	Yes	Approved. Please bring front wing to TC office for new QR code.
246	Women's Windsurfing	FRA	Tail wing and fuselage	31 JUL 2024 20:02	In a crash i got damaged on the front wing and the foil mast and when I checked the tail wing and the fuselage they have little damage too.	Yes	Approved. Damage seen by TC. Damage is genuine. Please take fuselage and rear wing to supplier for repair. TC does not need to see either piece of equipment once repair has been completed.
245	Women's Windsurfing	POL	front and back wing after crash	31 JUL 2024 19:52	please repair	Yes	Approved. Damage seen by TC. Damage is genuine. Please take foils to supplier for repair. TC does not need to see foils after repair is complete.
244	Men's Skiff	NZL	Rivets on boom	31 JUL 2024 19:34	The rivets on our boom are loose and we need to replace please	Yes	Repair approved. To be re-inspected before Medal Race



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
243	Women's Windsurfing	FRA	Foil mast Use + front wing Use / Fra Women	31 JUL 2024 19:24	Ask for repair of the foil mast + the front wing "Use" that were damaged on a crash on race 10. Depending the aspect of repair I will see tomorrow which equipment I can use.	Yes	Approved. Damage seen by TC. Damage is genuine. Please take front wing and foil mast to supplier for repair. Please return front wing as used on water to supplier. TC needs to see front wing before being returned to FRA women. TC does not need to see foil mast once repair has been completed.
242	Men's Dinghy	ESA	Bow stickers	31 JUL 2024 18:42	I would like to have some one fixing the sticker to make it smoother or cut the part that has ruined please	No	
241	Men's Windsurfing	NZL	iQ Foil Men	31 JUL 2024 18:25	we have broken the third lowest batten and would like a replacement please. We also sailed much of the day with this broken batten and the sail has deformed. we also request to change to our spare sail please.	Yes	BATTEN - approved. Broken batten seen by TC. Supplier to provide new batten to NZL. SAIL - rejected. No damage to sail.
240	Women's Skiff	NED	camera	31 JUL 2024 17:50	We lost one of the cameras today on the water.	Not decided	
239	Mixed Multihull	NZL	Nacra Foils	31 JUL 2024 17:37	We would like permission to fill and sand the starboard foil where the paint has been chipped. Can we have permission to do the repair in our container rather than the boat park please	No	See response to #237.
238	Mixed Multihull	NZL	Nacra Foils	31 JUL 2024 17:33	we would like permission to fill and sand the starboard foil where the paint has been chipped. Can we have permission to do the repair in our container rather than the boat park please	No	See response to #237.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
237	Mixed Multihull	NZL	Nacra Foils	31 JUL 2024 17:30	We would like permission to fill and sand starboard foil where the paint has been chipped. Can we have permission to take the foil from the boat park and do the repair in the container park? thanks	Yes	Approved. Starboard foil (ZS00975) is approved to be repaired in accordance with class rule limitations. Daggerboard is approved to be removed from boat park for purpose of repair only. Board needs to be presented to TC for checking by no later than Friday 2nd August @ 1000. Come to race office for the permission to leave the boat park document
236	Mixed Dinghy	USA	Hull	31 JUL 2024 16:05	May I polish my hull with McLube hullkote speed polish? Thank you	No	This form is to request replacements and repairs. Please use the RFI for other questions
235	Men's Dinghy	HUN	hull	31 JUL 2024 15:49	there are a few drops of dried gelcoat underneath the hull, near the centerboard case. it looks like some drops of gelcoat fell there from a case repair. we request that the supplier buffs them off.	Yes	approved to be fixed by the supplier
234	Mixed Multihull	USA	Spinnaker	31 JUL 2024 15:41	We request to use spinnaker tape to repair a 5mm pinhole on the leading edge of our spinnaker	Yes	Please present to the TC member for inspection UPDATE: Approved. Damage seen by TC. Damage is genuine. No need to re-inspection
233	Men's Dinghy	ISR	Ratchet block	31 JUL 2024 15:25	I would like the supplier to change the ratchet block because the Ronstan ring rope is torn	Yes	approved to be fixed by the supplier. No need re-inspection
232	Mixed Multihull	USA	Rudder - Maintenance	31 JUL 2024 15:12	We would like to undertake permitted maintenance as described in Class Rule C.8.2.i and sand the leading edge of the rudder blade to remove scratches in the paint. The scratches are in the region of 30 cm above the elevator.	Yes	Please present to the TC for inspection. UPDATE: Maintenance is permitted by the CR
231	Women's Windsurfing	NOR	0 shim	31 JUL 2024 14:59	I lost my 0 shim on the water, and asking for replacement for 0 shim	Yes	Approved. Please present new 0 degree shim to TC beach office for equipment control.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
230	Men's Windsurfing	ESP	IQ Foil M	31 JUL 2024 14:43	We resquest to repair sail with tape at the pocket of the batten. Thanks	Yes	Approved. Damage seen by TC. Damage is genuine. Please take sail to supplier for repair. TC does not need to see sail once repair completed.
229	Women's Skiff	POL	Mainsail	31 JUL 2024 14:31	We ask for permission to make a repair to our mainsail. We have a torn material next to the fifth batten and need to put some dacron tape to cover the hole.	Yes	Repair inspected and approved
228	Men's Dinghy	DEN	Centreboard Protection tape	31 JUL 2024 13:52	I would like to request to have replaced the front centreboard protection tape	No	this have been already approved. see item 212
227	Mixed Multihull	BEL	Maintenance in shade	31 JUL 2024 13:33	Request to do maintenance in an area where we can be in the shade (move away from the allocated boatpark) OR request to have an umbrella in the allocated boat park	Yes	Approved to do maintenance in the boat park in the shade. In case the option is to do the maintenance inside the tent, the tent shall remain open while the items are inside. Approved only on the 31/07/2024 until 18.00
226	Men's Windsurfing	LTU	Board damage	31 JUL 2024 13:12	After a catapulté on the race 4, board have a crack on the front starboard part. We are asking the possibility to fix it	Yes	Approved. Damage seen by TC. Damage is genuine. Please take board to supplier for repair. TC does not need to see board after the repair.
225	Mixed Dinghy	AUT	Gasket protection tape	31 JUL 2024 12:55	I kindly request to renew the gasket protection tape.	Yes	Please present the boat for inspection on 31.July 2024 at 15:00 Update 31/07/2024 - 14:50: boat has inspected - renewal of gasket tape has been approved No further inspection required
224	Men's Skiff	CHN	Gennaker	31 JUL 2024 12:16	The bottom corner my gennaker is broken and has a tear now, I kindly request a repair please. Thank you.	Yes	repair inspected and approved
223	Men's Dinghy	HUN	centerboard case padding glue	31 JUL 2024 12:12	the adhesive strip in front of the centerboard case fell off while sailing, leaving some residual glue. the leading edge of the centerboard is also stained with glue. we request that the supplier cleans off the glue marks from the case and centerboard.	Yes	Approved to be fixed by the supplier
222	Women's Dinghy	BEL	Centreboard front friction pad	31 JUL 2024 12:10	Request to renew the centreboard front friction pad	Yes	Approved tobe fixed by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
221	Men's Windsurfing	BRA	Foil mast	31 JUL 2024 12:04	We are not satisfied with the repair of our racing mast and we believe it will break again. We request to change it by our spare mast foil.	Yes	Approved. Further to discussion between BRA men, TC and supplier, agreed by TC to replace foil mast with spare foil mast. Race foil mast returned to supplier. New spare foil mast provided to BRA men - QR code SC643171
220	Men's Dinghy	ESA	Bow stickers	31 JUL 2024 11:44	The front part of my bow stickers have been unglued by the friction of the trolley I would like to repair them please	No	
219	Mixed Multihull	CHN	The port tack of the hull's Non-slip mat	31 JUL 2024 11:40	Hi Technical committee, I am from China, Nacra 17 sailor , the port tack of our hull's non-slip mat was broken and we require to repair that, many thanks.	Yes	approved to repair in the boat park. No re-inspection is needed
218	Men's Dinghy	BEL	Traveller wear pads	31 JUL 2024 11:36	Request to remove the black traveller wear pads from the traveller.	Yes	
217	Men's Windsurfing	GBR	Front wing SC441331	31 JUL 2024 11:14	QR CODE REPLACEMENT	Yes	Approved. Please bring foil to TC office for a new QR code.
216	Men's Windsurfing	BRA	IQ foil Mast broken	31 JUL 2024 11:10	We all received 4 complete foil sets. In the first day of testing my first foil mast broke, leaving me having to choose between 3 foil masts. The day before the first day of competition I had a crack in my racing mast. The mast was then repaired. I went racing the first 2 days with the foil mast and the damage mast broke again giving me a disadvantage on the last races of the day yesterday. Considering the situation, my spare foil mast for this regatta (my third option) is very bad, and I do not want to race with my spare mast, I would like to get a new mast provided by the supplier, so I am finally in equal conditions with all the other competitors , that have 4 choices while I have one repaired for the second time and only other two that are bad.	No	TC has approved two repairs of the race foil mast for BRA men. The repairs have been accepted both times by BRA men. ER 7.1.10 requires that if the race foil mast requires replacement, it shall be replaced with the registered spare foil mast.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
215	Men's Windsurfing	SVK	Boom	31 JUL 2024 11:02	My screw on the back of the boom got lose I would to ask you to repair it officially	Yes	Approved. Damage seen by TC. Damage is genuine. Please take boom to supplier for repair. TC does not need to see boom once repaired.
214	Mixed Multihull	ESP	Mixed multihull	31 JUL 2024 10:28	We kindly request to extend until the last equipment inspection slot the deadline of your previous permission (31 July 12:00). With the conditions that we have here at the Container we need extra time. Thanks for your understanding.	Yes	approved to bring the foils to the inspection not later than 31/07/2024 at 16:00
213	Men's Dinghy	SGP	Centerboard case tape protection	31 JUL 2024 10:12	Request to get Ferdi to help me replace a new front centerboard case tape as mine is coming off	Yes	Approve for supplier to replace centreboard case front protection tape
212	Men's Dinghy	DEN	Back Centreboard stopper	31 JUL 2024 10:06	I would like to request to have the back centreboard stopper replaced as it has been worn out	Yes	Approve for replacement of centreboard friction pad by the supplier
211	Men's Dinghy	DEN	Hull	31 JUL 2024 10:04	I would like to request to have repaired a small gelcoat damage under the bow of the hull	Yes	Damage reviewed Approve to repair of hull by the supplier Sailor can bring his boat with equipment to the supplier's hanger for the repair No re-inspection is required
210	Men's Dinghy	FRA	Friction tape for centreboard	31 JUL 2024 8:16	My friction tape need to be change. Thanks Jb	Yes	Approve to replace centreboard tape by the supplier
209	Men's Skiff	ESP	Centerboard	30 JUL 2024 18:24	Centerboard was damaged with a small hole, i request permission to repair it	Yes	Repair to daggerboard is approved. To be re-inspected before delta for the Men's Skiff event on 31/07/2024.
208	Men's Skiff	URU	Centerboard case	30 JUL 2024 18:20	We kindly ask permission to perform minor repairs on the bottom part of the centerboard case. Minor damage caused while racing	Yes	Repair to lower daggerboard case packing permitted to the extent permitted by Class Rule C.7.1(j). Boat may be moved from its allocated boat park area to facilitate the repair, but shall remain within the boat park. To be re-inspected before delta for the Men's Skiff event on 31/07/2024.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
207	Men's Skiff	AUT	daggerboard case	30 JUL 2024 18:05	we request that we can repair our daggerboard case due to damage that occured today. in order to repair the damage, we kindly ask that the boat may be moved from its allocated place but will remain in the boat park.	Yes	Repair to lower daggerboard case packing permitted to the extent permitted by Class Rule C.7.1(j). Boat may be moved from its allocated boat park area to facilitate the repair, but shall remain within the boat park. To be re-inspected before delta for the Men's Skiff event on 31/07/2024.
206	Women's Windsurfing	CRO	Back wing	30 JUL 2024 17:49	QR code missing on the back wing. Kindly request replacement.	Yes	Approved. Please take rear wing to TC for new QR code to be applied.
205	Women's Windsurfing	ISR	Boom	30 JUL 2024 17:39	One screw in the end of the boom is loose, I'm asking if you can put some glue and screw it back Thanks.	Yes	Approved. Damage seen by TC. Damage is genuine. Please take boom to supplier for repair. TC does not need to see boom after repair.
204	Women's Dinghy	USA	Deck Mount Cleats	30 JUL 2024 17:17	We would like the supplier to check the fore and aft screws on the deck mount cleat. If they are loose, we would like the supplier to tighten the screws and secure the mount. Thanks!	Yes	approved to be repair by the supplier
203	Women's Windsurfing	SWE	Board	30 JUL 2024 17:09	There is a small crack in my board that needs to be repaired. It is on the bottom 3/4 of the way from the stern, near the edge of board. A ding about 2 cm in diameter.	Yes	Approved. Damage seen by TC. Damage is genuine. Please take board to supplier for repair. TC does not need to see repair once completed.
202	Mixed Dinghy	USA	Mainsail	30 JUL 2024 16:51	I am requesting permission to make a small repair to our main sail that has come back from branding damaged. Thank you!	Yes	Please present the sail for inspection on 31.July 2024 at 10:00 . Update: 31/07/2024 10.13 TC inspected and the damage is genuine. approved to be repaired in the inspection area. No need to be re-inspected



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
201	Women's Skiff	FIN	Footstraps bolts	30 JUL 2024 16:45	We broke plastic washer plate on starboard footstrap. We would like to replace broken plate with stainless steel washers on both port and starboard side. Manufacturer's footstrap installation solution is not strong enough... We kindly ask you for a permission to do the maintenance. Thank you in advance.	Yes	Damage seen by TC. Damage is genuine. approved to be repair. to be presented to the TC before the next first schedule race of the day.
200	Men's Windsurfing	DEN	Plastic cap on mini tuttle	30 JUL 2024 16:26	The plastic cap that goes around the mini tuttle is squeezed thin on the top and has finally broken. I would like to replace it with a new one	Yes	Approved. Please see supplier for replacement mini tuttle. TC does not need to see mini tuttle or its fitment.
199	Men's Windsurfing	BRA	Foil Mast	30 JUL 2024 16:06	Our foil mast is braking again close to the mast case.	Yes	Approved. Damage seen by TC. Damage is genuine. Please take foil mast to supplier for repair. TC will need to see foil mast before being returned to BRA men.
198	Men's Windsurfing	ITA	iQFoil M. Boom	30 JUL 2024 16:05	After the start of race 3 the boom snapped. I was then given a new boom by TC.	Yes	Replacement approved. Damage seen by TC on the water and replacement approved. Please take broken boom to supplier. Please show replacement boom to TC for checks before further use.
197	Men's Windsurfing	FIN	frontwing: SC 151 751	30 JUL 2024 16:03	requesting to have a small repair on frontwing. I hit something in the water between slalom and courseracing, and leading edge have some small damage	Yes	Approved. Damage seen by TC. Damage is genuine. Please take wing to supplier for repair. TC does not need to see front wing after repair.
196	Women's Dinghy	TUR	Mast bottom section measurement sticker is ripped	30 JUL 2024 16:00	We kindly request to have it replaced by a new one	No	The event limitation sticker has been reviewed. the numbers on the stickers are intact and clearly visible; therefore no replacement of the sticker is required.
195	Men's Dinghy	GBR	Friction pad on front of daggerboard case	30 JUL 2024 15:56	I request to have the friction pad on my boat changed by the supplier, it has worn through and is ripped/holed. Thanks GBR Men's single handed Dinghy	Yes	Approved for the supplier to replace the daggerboard front pad



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
194	Women's Skiff	SWE	Trapeze loop	30 JUL 2024 15:54	Requesting to exchange port trapeze wire (the rope that goes through the spreader) due to damage.	Yes	
193	Mixed Dinghy	GBR	Main halyard	30 JUL 2024 15:53	Replace broken main halyard that broke during training today	Yes	Replacement is approved. Further check is required after replacement . Please present the replaced equipment on 31 July at 10:15 for inspection. Update: 31/07/2024 10:15 The replacement has been inspected and approved. No further inspection required.
192	Men's Dinghy	IND	Rudder stock	30 JUL 2024 15:52	Would like to request to please adjust the rudder by the supplier	Yes	Approved for the supplier to adjust the rudder retaining flap
191	Men's Dinghy	NOR	Damage in mast hole	30 JUL 2024 15:51	I have gotten a damage inside the mast hole of my boat and would like the boat supplier and measures to look at it so we can decide what to do.	Yes	Damage reviewed Repair by the supplier is approved Sailor can move his boat plus all equipment to the supplier hanger for the repair
190	Women's Skiff	CAN	Mast track repair	30 JUL 2024 15:41	Can I repair my broken mast track please? I'm past the protest time limit due to the long sail in with strong winds. We went as fast as possible	Yes	Damage seen by TC. Damage is genuine. need to be presented to the TC before the first schedule race of the day. UPDATE: Mast have been presented after the repair and approved
190	Women's Skiff	GBR	Centreboard	30 JUL 2024 15:41	To substitute race centreboard for spare centreboard due to severe damage.	Yes	Please present the centreboard to the TC for inspection. UPDATE: Damage seen by TC. Damage is genuine. new daggerboard presented and approved to be replaced. New serial number:505753
189	Mixed Dinghy	SUI	mast halyards	30 JUL 2024 15:40	we would like to take down the mast, inside of the boat park, to clear the halyards. Thanks	Yes	No replacement is approved. The approval is limited with reorganizing the halyards for resolve entanglements. No re-inspection needed



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
188	Women's Skiff	POL	Tiller extensions	30 JUL 2024 15:38	We kindly ask permission to make repairs to both of our tiller extensions that got loosen after today's racing.	Yes	Damage seen by TC. Damage is genuine. No need to re-inspection
187	Women's Skiff	POL	Caps (top shrouds)	30 JUL 2024 15:34	We have a damage to our caps and therefore kindly ask a permission to replace both caps.	Yes	30/07/2024:Damage seen by TC. Damage is genuine. approved to be replaced, no need to be re-inspected.
186	Women's Skiff	POL	Gennaker	30 JUL 2024 15:33	After Race 8 we have notified the TC/RC that we have to replace our gennaker due to damage and received the acknowledgment via VHF radio. Our coach also received verbal confirmation from the measurer. The gennaker we replaced after Race 8 is however unsuitable for further racing therefore we kindly request the permission to make another replacement of our gennaker.	Yes	30/07/2024 : please come to see the TC when the 49er return ashore. Damage seen by TC. Damage is genuine. approved to change the spare Gennaker as sailing Gennaker and to replace the spare gennaker for a new one. Present the new spare gennaker for inspection before delta for the Women's Skiff event on 31/07/2024.
185	Women's Skiff	CZE	Trolly	30 JUL 2024 15:26	We broke our trolly, we request a permission to change the trolly	Yes	
184	Women's Skiff	CZE	Hull	30 JUL 2024 15:26	We have a small whole on our boat on the starboard part of the bow. We request a permission to fix it	Yes	30/07/2024: please present your boat in your boat allocated area at 30/07/24 -16:15 Damage seen by TC. Damage is genuine. Request to repair in teh boat park approved
183	Mixed Dinghy	ITA	Self bailer	30 JUL 2024 15:16	Request to clean the self bailer on the hull from the rust, by cleaning	Yes	Approved as to be done in the boat park without using sand paper or any other hard abrasive material. No re-inspection need it
182	Women's Windsurfing	MEX	Board	30 JUL 2024 14:09	Dear Technical Commitee, I would like to ask for a repair on the front of my board with serial number: ST24IQF0C95B24010011 Thank you Mariana	Yes	Approved. Damage seen by TC. Damage is genuine. Please take board to supplier for repair. TC does not need to see board after the repair.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
181	Men's Dinghy	GER	ILCA 7 bailer	30 JUL 2024 12:32	My bailer in my ILCA 7 doesn't close properly. I kindly request repair by the supplier. Thx, Philipp	Yes	Approved to be replaced by the supplier
180	Women's Dinghy	FRA	Plug	30 JUL 2024 12:16	My plug was stolen. Asking for a new one from the supplier.	Yes	Approved to be replaced by the supplier
179	Women's Dinghy	NZL	ILCA 6 drain bung	30 JUL 2024 11:39	the drain bung on our ILCA 6 has gone missing. Can we obtain a new one please from the suppliers please Thanks	Yes	Approved to be replaced by supplier
178	Men's Dinghy	IRL	Centre board protector	30 JUL 2024 11:26	My centre board protector on front of centre board case fell off and I need a new one	Yes	Please present the boat to the TC for inspection. Updated: Approved to be replaced by the supplier
176	Mixed Multihull	ESP	Mixed multihull foils	30 JUL 2024 10:59	We request to be able to remove the foils from the boat allocated area and take them to the container park.	Yes	Permission is granted to take the equipment out of the boat park and to the container park on 30 July 2024 until 31 July 2024 12:00
175	Men's Dinghy	HUN	cunningham rope	30 JUL 2024 10:38	we wish to change one of the ropes in the cunningham system as it is a bit worn. it is an athlete supplied item	Yes	Worn out rope and replacement new rope have been inspected Replacement is approved
174	Men's Windsurfing	DEN	Plastic cap mini-tuttle	29 JUL 2024 19:52	The plastic cap around the mini-tuttle has moved after sailing today and is No longer flush. I think the plastic has stretched. Can I trim it flush again?	Yes	Approved - note that ER 7.8.1.2 permits this modification without written approval by the TC.
173	Men's Windsurfing	GBR	Front wing	29 JUL 2024 18:54	QR code came off, please can it be replaced. Thanks (Original QR code = SC441331)	Yes	Approved. QR code replaced. New QR code is SC 588432
172	Men's Windsurfing	FRA	Top batten (1) of the USE Sail	29 JUL 2024 17:46	Top batten got broken today on the water. Needs a replacement	Yes	Approved. Damage seen by TC. Damage is genuine. Please collect replacement batten #1 from supplier. Noted new code for batten #1 is SV001675
171	Men's Skiff	GBR	Daggerboard	29 JUL 2024 17:46	Permission to repair the scratches, as seen by measurer, in in dinghy park	Yes	Repair to daggerboard in the boat park allocated area is approved. Daggerboard to be re-inspected before the next scheduled race.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
170	Men's Windsurfing	DEN	Rear Wing	29 JUL 2024 17:40	My rear wing broke on the water and I will request to use my spare wing from now on. Additionally I will request my new spare wing to be SC 346 782	Yes	Approved. Damage seen by TC. Damage is genuine. On water replacement shall be returned to supplier. Noted that new race rear wing is SC 291544 and new spare rear wing is SC 346782.
169	Men's Windsurfing	SVK	Front wing	29 JUL 2024 17:40	I would like to change my Front wing due to damage New race wing: SC 059 483 New spare wing SC 118181	Yes	Approved. Damage seen by TC. Damage is genuine. On water replacement shall be returned to supplier. Noted that new race wing is SC 059483. New spare wing is SC118181.
168	Men's Windsurfing	JPN	Front Wing QR code: SC001254	29 JUL 2024 17:38	The front wing got scratched due to the contact with FRA boat at the first start of Race1. Can I ask the supplier to repair it?	Yes	Approved. Damage seen by TC. Damage is genuine. Please take front wing to supplier for repair. TC does not need to see repair before collecting from supplier.
167	Women's Windsurfing	NZL	Mainsail damage	29 JUL 2024 17:35	We have suffered a 40cm tear in the luff of our mainsail which we repaired while on the water with stickyback. we would like to either make a more permanent repair, or have permission to use our spare sail. please let me know what we can do	Yes	Please bring your spare sail to be branded to the Grapefruit office in building 1. @@ UPDATED @@ Tuesday 30th July @ 0825 Damage seen by TC. Damage is genuine. Replacement of sail approved. Please take replacement sail to Building 1 for "Look of the Games" to be applied. Sail will be ready for collection from TC office by 0915. New spare sail should be collected from supplier - new spare sail is 9216963
166	Women's Skiff	JPN	Starboard wing	29 JUL 2024 17:34	It needs to repair.	Yes	Repair to port wing in the boat park allocated area is approved. Wing to be re-inspected before the next scheduled race.
165	Men's Windsurfing	NED	Board	29 JUL 2024 17:33	To repair nose of the board, due to a crack caused by a crash prior to race 1.	Yes	Damage seen by TC. Damage is genuine. Please take board to supplier for assessment of on-water repair carried out by NED coach. Supplier to determine if further repair required or not. TC does not need to see board if supplier decides a repair is required.
164	Men's Skiff	CHN	Request of Gennaker Repair	29 JUL 2024 17:32	The top corner of my gennaker is broken, I kindly request to repair.	Yes	Repair to gennaker in the boat park allocated area is approved. Sail to be re-inspected before the next scheduled race.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
163	Mixed Dinghy	USA	Hull	29 JUL 2024 17:31	I am requesting permission to repair gel coat damage to our bow. Thank you!	Yes	please present the boat to the TC for inspection. TC inspected the boat. damage is genuine. Repair approved.
162	Men's Windsurfing	JPN	Rear Wing QR code:SC177716	29 JUL 2024 17:27	The edge of the rear wing was cracked due to the contact with FRA boat at the first start of Race1. Can I ask supplier to repair it?	Yes	Approved. Damage seen by TC. Damage is genuine. Please take rear wing to supplier for repair. TC does not need to see repair before collecting from supplier.
161	Men's Skiff	AUT	Mainsail	29 JUL 2024 17:24	we request to repair the mainsail due to damage in the upper part of the leech. in order to repair it properly we kindly ask that we are allowed to take the mainsail out of the boatpark and return it as soon as possible after the repair is done.	Yes	Repair to mainsail outside of the boat park is approved. Sail to be re-inspected in the boat park allocated area before the next scheduled race.
160	Men's Skiff	GBR	Daggerboard	29 JUL 2024 17:21	Permission to clean / buff dirt / grease from daggerboard	No	Cleaning is not permitted by the class rules.
159	Women's Skiff	NZL	FX Skiff, NZL	29 JUL 2024 17:01	we would like to replace the broken bungy on the tiller extension retainer	Yes	Replacement elastic approved to the extent permitted by CR C.6.1(b). No further inspection necessary.
158	Mixed Dinghy	SLO	Repair the gasket	29 JUL 2024 16:28	thanks We are kindly asking to be able to repair the gasket on our racing boat because we saw damage during the measurement inspection. We are kindly request to repair it.	Yes	Approved to be repair in the boat park
157	Men's Dinghy	PER	Bailer	29 JUL 2024 16:04	Request for the supplier to clean the silicone on the sides of the bailer when it is open. No need to take the bailer out.	Yes	Approved to be cleaned by the supplier
156	Men's Dinghy	SGP	Centerboard friction pad	29 JUL 2024 15:45	Request for permission to change centerboard friction pad as i realized the pad has worn out significantly	Yes	Approved to be changed by the supplier
155	Men's Dinghy	ARG	scratch in the boat	29 JUL 2024 13:57	We found the bottom edge at the stern with a scratch which we would like to repair, by the supplier	Yes	approved to be repair by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
154	Men's Dinghy	NOR	Request to get a new piece of tape in front of centerboard case	29 JUL 2024 13:23	The piece of tape which came with the boat fell off last training session and I request for the boat supplier to be allowed to put a new one.	Yes	approved to be fixed by the supplier
153	Mixed Multihull	AUS	Helmet	29 JUL 2024 12:24	Request permission to take helmet to container area to apply bright material for compliance with class rules.	Yes	Approved
152	Mixed Dinghy	SUI	to TC - Hull cleaning	29 JUL 2024 12:02	About ER 7.3.5: a) can normal commercial vinagre be used to clean the hull? b) can commercial anti-calc (like Viakal) be used to clean the hull?	No	This form is to request equipment substitutions and repairs. Please use the proper channel for question (RFI)
151	Men's Dinghy	ARU	Friction pad front of the centreboard case	29 JUL 2024 11:42	Friction pad is worn out and I would like to have it replaced.	Yes	approved to be repair by the supplier
150	Women's Dinghy	CAN	Rudder	29 JUL 2024 10:45	I'd like to get the damage on my rudder repaired	Yes	Approved to be repair by the supplier
149	Men's Dinghy	IVB	Goose neck bolt	29 JUL 2024 10:18	Tightened and filed	Yes	To be repair by the supplier during inspection today
147	Men's Dinghy	KOR	friction pad for centerboard	29 JUL 2024 9:52	the friction pad needs to be replaced	Yes	approved to be fixed by the supplier
146	Men's Skiff	HKG	Pulley Block on boom	29 JUL 2024 9:47	We need to replace the block as the bearing stopped working.	Yes	Replacement block and addition of security lines to the extent permitted by Class Rules C.6.1(h), C.6.1(i) and C.6.1(k) is approved. No further inspection necessary
145	Women's Dinghy	HUN	centerboard friction tape in front of case	29 JUL 2024 8:56	the centerboard is not holding very well in the case. we would like to have the little strip of non-skid tape in the front replaced. is the tape considered to be "adhesive tape" and can be replaced (within the class rules) by the sailor herself or does it have to be done by the supplier?	Yes	Approved to be fixed by the supplier
143	Men's Dinghy	IVB	Outhaul System	28 JUL 2024 23:31	Requesting to replace current outhaul lines with newer ones. System, line types and blocks remain exactly the same.	Yes	Approved to be inspected by TC during the inspection today
142	Men's Dinghy	ARG	bailer	28 JUL 2024 22:36	the bailer is not closing completely. I need to the supplier fix it please.	Yes	Approved to be fixed by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
141	Mixed Multihull	JPN	Notice number 34	28 JUL 2024 22:15	For Nacra17 Japanese crew name Given name: Oura Family name: Nishida Capiglia Please correct it for the panel stickers.	Yes	Request noted and it is forwarded to Grape Fruit to be corrected
140	Men's Dinghy	IVB	Centerboard stopper at aft of case	28 JUL 2024 19:53	Requesting to receive a new centerboard friction pad as the current one is worn and prevents centreboard from being tight.	Yes	Please present the case to your ITO for inspection Update: Approved to be fixed by the supplier during the inspection today
139	Men's Dinghy	SGP	Centerboard friction pad	28 JUL 2024 19:53	Requesting to get supplier to help adjust friction pad forward as centerboard is slipping up	Yes	Approved to be fixed by the supplier
137	Women's Dinghy	SAM	Bow of hull	28 JUL 2024 19:07	Another boat backed into the bow of my hull. I would like to request a gel coat and patch of the bow.	Yes	28/07/2024: the damage has been inspected Repair by supplier is allowed (this includes permission to move boat from boat park allocated area)
136	Men's Dinghy	GER	ILCA 7 centerboard case	28 JUL 2024 19:06	I kindly request approval to get a new piece of rubber tape in the top front corner of the centerboard case, as the supplied one fell off during today's training. Thx Philipp	Yes	28/07/2024 replacement by supplier is approved
135	Men's Skiff	BRA	Port wing	28 JUL 2024 18:17	There is a crack in front of our port wing. We need to repair it with a little of gelcoat and replace the non-skid tape.	Yes	Repair to leading edge of port wing in the boat park allocated area is approved. no further inspection necessary.
134	Men's Dinghy	IVB	ILCA Hull	28 JUL 2024 17:38	Chip in daggerboard trunk at deck level.	Yes	Damage noted To be fixed by the supplier
133	Women's Dinghy	NOR	Sail	28 JUL 2024 17:27	Asking for permission to change the sticker in the sail with my name. The name is misspelled and I would like to change it to my correct name.	Yes	Request noted - TC will forward it to Grapefruit and provide information once available in the venue



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
132	Women's Windsurfing	NED	boom & black tape scratched	28 JUL 2024 17:18	On the shore, during postponement I put my sail next to the tent. One of the sailors moved my sail, it fell off on the concrete block and the boom got scratched. Also, the black tape to cover the boom logo got scratched and needs replacement.	Yes	Please present the boom to the TC at the beach office on 29/07 at 9.00 @@ UPDATED @@ Tuesday 30th July @ 0825 Boom seen and black tape replaced. No further action required.
131	Mixed Dinghy	GER	Spinnaker pole up haul hook.	28 JUL 2024 17:01	We would like to change this fitting that is not working well. This is before our equipment inspection.	Yes	28/07/2024: repair is allowed. Equipment will be checked at the time of pre-event equipment inspection
130	Women's Dinghy	TUR	Boom	28 JUL 2024 16:41	My supplied boom is bent. I would like to chance it.	Yes	28/07/2024: the equipment has been inspected and replacement by supplier is approved
129	Men's Dinghy	POR	Boat	28 JUL 2024 16:19	We need to switch the bailer of Ilca 7 Portugal it came off	Yes	TC inspected and approved to be repair by the supplier
128	Women's Skiff	GBR	49er FX hull	28 JUL 2024 16:02	Please may we add insignia tape to the c/b packing? Can we also request to check the board fit on the water in the marina?	Yes	The daggerboard case packing may be replaced with any material. Additional material may be added to the extent permitted by CR C.7.1(j). The boat may be launched and board fit checked inside the marina.
127	Mixed Dinghy	TUR	Repair the gasket	28 JUL 2024 14:13	we are kindly asking to be able to repair the gasket because we saw damage during the measurement inspection . WE kindly request to repair it	Yes	Approved to be repair in the boat park
126	Men's Dinghy	POL	centerboard anti slip tape	28 JUL 2024 14:37	Hello, I would like to change my centerboard anti slip tape, because it fell off.	Yes	to be replaced by the supplier
125	Women's Windsurfing	HKG	Batten no5	28 JUL 2024 14:28	I broke the batten no5 in the water , replaced by new batten from supplied equipment boat.	Yes	Replaced on the water approved



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposonse
124	Women's Dinghy	POL	Cockpit bailer and bung	28 JUL 2024 14:02	May I request a service of the auto bailer as it is not closing properly. In addition the bung appears to be too small for the drainage hole and does not seal the cockpit as intended. I would like to request a change for an alternative bailer bung or my own.	Yes approved to be replaced by the supplier
123	Men's Dinghy	ISR	Anti slip centre board case	28 JUL 2024 13:59	I would like the supplier to replace the torn anti slip at the front of the CB case	Yes Approved to be replaced by the supplier
122	Women's Dinghy	POL	Forward centerboard friction pad	28 JUL 2024 13:58	May I request a change of the forward centerboard friction pad as mine is worn out and not working as intended. Thank you	Yes to be replace by the supplier
121	Men's Dinghy	NOR	Change of friction pad	28 JUL 2024 12:21	My centerboard has broken through the friction pad so it is starting to be cut into two pieces. I would like to ask for permission for the supplier of our ilca's to change it for a new one.	Yes 28/07/2024: the broken friction pad shall be replaced by the supplier. Please present your boat to the supplier (This includes the permission to move the boat out of its boat park allocated area)
120	Men's Dinghy	MNE	Hull(cockpit)	28 JUL 2024 12:06	I would like to repair my boat. The gelcoat inside the cockpit has been damaged during the training last couple of days and I would like to be repaired by the supplier. Thanks	Yes 28/07/2024 - the equipment has been inspected Approval is given for repair by the supplier
119	Men's Dinghy	ARG	hiking strap	28 JUL 2024 11:57	i need to change from the hiking strap provided to my own hiking strap please	Yes The toe strap may be supplied by the athlete provided it conforms to the Class Rules, but shall be fitted by the supplier. Please present your boat to the supplier; this includes the permission to move the boat out of its allocated boat park area
118	Mixed Dinghy	SUI	Mixed Dinghy - Hull - Stern edge	28 JUL 2024 11:52	We ask permission to make a small fix on the stern edge, close to the rudded position, after the measurement stage	Yes 28/07/2024: the hull damage has been inspected. Permission is granted to perform the repair of the described damage.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposonse
117	Women's Dinghy	GER	Sail branding	28 JUL 2024 11:40	Hello, I picked up my sail with the Olympic branding. When unrolling it I realised that my name is misspelled. The sticker says BUESSELLBERG instead of BUESSELBERG. I request to have the sticker replaced please. Thank you.	Yes You will receive instructions as soon as possible.
116	Men's Windsurfing	SUI	Iqfoil boom SB 675406 SUI men	28 JUL 2024 11:31	Today the QR code of my IQfoil boom, SB 675 406, came off. Ask for new QR code.	Yes Approved New QR code: SC 697086
115	Women's Windsurfing	POL	Helmet	28 JUL 2024 11:11	Can I put silver bright tape on my white helmet to make sure I comply with CR? My helmet was checked and passed through equipment inspection.	Yes Class Rule C.3.2(a)(i) requires a helmet to have a brightly coloured region of at least 300 square centimetres of the exterior surface (please read C.3.2(a)(i) for full text). This may be achieved by the colour of the helmet itself or by adding brightly coloured material - such as silver bright tape. Please see NoR 9.5 for competitors responsibility on compliance with class rules and the equipment inspection process.
114	Men's Dinghy	HUN	hull	28 JUL 2024 10:51	yesterday, i sent a request for gelcoat repair on HUN ILCA 7 port side aft corner. i did not receive any email notification of this request. if you have already received this request, pls ignore	No This request have been already been answered. Please go to your ITO in the hangar 2
113	Mixed Dinghy	GRE	Boat	28 JUL 2024 10:00	Kindly permit moving boat from boat park to the container for repairs.	No 28/07/2024: please present your boat on 28/07/2024 at 13:30 in front of the 470 inspection area for inspection of the damage.
112	Women's Dinghy	AUS	Vang rope	28 JUL 2024 9:57	Request to replace vang rope due to damage.	Yes Please present the item to your ITO for inspection. Update: Vang rope inspected by TC and approved to be replaced.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
111	Men's Dinghy	FRA	Hull Ilca 7	28 JUL 2024 9:53	My hull as a damage from building side. I ask for repair	Yes	Please go to you ITO to verify the damage 28/07/2024: approved to be repaired by the supplier. This includes the permission to move the boat out of its boat park allocated area. No inspection following repair required
110	Men's Dinghy	ARG	hiking strap	27 JUL 2024 22:34	the ILCA 7 strap as the current one (provided) does not meet expectations. We have already spoken to the official supplier and he told us that he has no problem with it. He just needs official approval Thank you very much.	Yes	27/07/2024: Please clarify your request 28/07/2024: Refer to request 119
109	Men's Dinghy	ISR	Bailer	27 JUL 2024 20:18	I would like to glue the aft part of the bailer	No	Please go to the supplier to fix it
108	Women's Dinghy	BEL	Vang	27 JUL 2024 18:05	On the vang bottom block, the right-hand cleat spring is malfunctioning and does not close automatically. Request to change the bottom vang block.	Yes	27/07/2024: To present the above mentioned equipment for review by ITO at 1200hr outside ILCA measurement hanger please 28/07/2024: The equipment has been presented for inspection. The requested replacement of the bottom vang block is approved
107	Men's Dinghy	GER	Friction pad replacement aft end of centerboard case	27 JUL 2024 17:20	I am requesting to get a replacement friction pad in my CB case as the current one is worn out. Thx, Philipp	Yes	Approved to be fixed by the supplier during pre-event equipment inspection
106	Women's Skiff	NZL	NZL FX rigging	27 JUL 2024 16:47	The rope that holds the halyard adjusters onto the gooseneck is worn. Can we replace this rope with a new piece of similar characteristics (3mm dyneema).	Yes	Replacement rope is approved. No inspection necessary
105	Women's Skiff	GBR	Skiff hull and foils	27 JUL 2024 16:21	Re RFI 105. Once hull and foils have been rinsed with water, Are we also permitted to remove the water with a squeegee / towel to prevent build up of water / salt residue on the surfaces?	Yes	



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposeonse
104	Men's Skiff	BEL	Hull & mast	27 JUL 2024 16:11	We request permission to use "finish-cleaner" to remove residue from the hull and mast.	No
103	Men's Skiff	CHN	49er	27 JUL 2024 16:06	One of my corrector weights has been unclear and illegible. Could you please rewrite it for me? Thanks	Yes See item 96
102	Women's Dinghy	AUS	Hull "Look of Games" sticker	27 JUL 2024 16:03	Request replacement of Look of Games sticker - bow, port side.	Not decided
101	Men's Skiff	GBR	Hull	27 JUL 2024 15:58	Our boat has been sat in the Olympic venue since the 7th July. Please may we have permission to clean the boat with soap and water to clean off any dust/oil that has accumulated over that time. And also permission to dry once we have rinsed off the soap.	No
100	Men's Windsurfing	AUS	Hull	27 JUL 2024 15:35	Request to repair or replace hull, based on hull box being outside of width tolerance.	Yes Damage seen byTC on board. Board cannot be repaired so replacement board approved. New serial number is "0044". Board checked and measured for compliance. New event limitation sticker is 0104.
99	Men's Windsurfing	GBR	Sail Battens	27 JUL 2024 15:33	Could the serial number of my battens: SV003633 please be verified. The battens looked like they were removed by the branding supplier and I want to double check they were not replaced with another competitors by accident. Thank you	No This is not a request for repair or replacement. Please TC in beach office or submit an RFI.
98	Men's Windsurfing	AUS	Hull box / hull appendage	27 JUL 2024 15:09	Request permission to shim sides of hull box in compliance with CR 7.1(c).	No See response to request 100. C.7.1(c) applies for the event without requiring permission.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
97	Women's Windsurfing	MEX	Sail	27 JUL 2024 15:08	Dear Technical Commitee, I would like to ask for a repair on my sail SC 8862 413. The zipper of the sail (where the boom is) broke. Regards, Mariana	Yes	Damage seen by TC. Damage is genuine. Repaired approved by supplier. TC does not need to see repair.
96	Men's Skiff	CHN	49er	27 JUL 2024 13:23	I found my lead is loose after training, and the signature is becoming vague. May I request to check the lead and sign again please? Thank you.	Yes	Correctors have been re-weighed and re-signed by the TC. Correctors shall be fixed to the boat as required by CR C.7.4
95	Women's Windsurfing	NED	washers	27 JUL 2024 12:53	The two supplied washers that we were given (notice 09 refers) were bent after one session yesterday. We would like to request new ones or receive permission to use our own. Photos available if required.	Yes	Approved. Class Rule C.8.1(b) permits that the provided bolts and washers may be replaced provided they are of the same size. If not the same size then please see the supplier and swap damage washers for new washers.
94	Men's Dinghy	HUN	Centerboard friction pad	27 JUL 2024 12:48	The centerboard friction pad has been moved a few times and the holes have elongated so that it no longer holds the centerboard firmly. we would like to have it replaced, please	Yes	Please come to hanger 1 out side building one today 27/07/2024 at 16.00 to meet the Dinghy TC. UPDATE: TC inspected and it is not repairable. Approved to be replaced by the supplier
93	Women's Dinghy	FRA	Rudder ILCA6	27 JUL 2024 11:44	My rudder is making some noice and vibration. I would like to have the supplier have a look on it.	Yes	Approved to be fixed by the supplier.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
92	Women's Windsurfing	NZL	IQ Foil women	27 JUL 2024 11:40	I would like to get clarity regarding the two answers to #79 and #80 requesting substitution of the supplied foil system bolts and washers with our own. The answer given appears to deviate from the class rules by specifying a screw driver tip to tighten these bolts. Is this what is intended? Request 80 was to clarify the use of traditional hex head bolt rather than the supplied machine screws with torx head and this request was denied. To conform with the class rules this request should have been approved. Many thanks	Yes	Request 79 granted permission to use alternative bolts and washers provided they were of the same size as that provided by the supplier. The method of adjusting the tension in the bolt is not prescribed.
91	Men's Windsurfing	BRA	Foil Mast	27 JUL 2024 11:40	We have a small crack on our mast close to the QR code. Please we need your expertise to do the best solution. Thank you!	Yes	Foil mast inspected by TC. Damage is genuine and repair approved by the supplier. TC shall inspect repair before being returned to BRA men.
90	Men's Skiff	CHN	49er	26 JUL 2024 20:23	Dear Sir, According to the ER3.1, as I have my equipment check finished, I am wondering if I may change a kind of fittings(pieces of metal with plastic were damaged)to fix the steel wire to spreaders of 49er boat. Thanks	Yes	
89	Women's Skiff	FRA	Centerboard + rudder	26 JUL 2024 17:41	We need to repair centerboard and rudder at the container	Yes	Please bring the foils for inspection at the 49er measurement area on 27/07/24 at 10.00 Update - 27/07: The foils have been inspected and are approved for repair in the container park to the extent permitted by Class Rule C.8.1(d). Foils to be presented for re-inspection at the 49er measurement area before 1100 on 28/07.
88	Men's Windsurfing	BRA	Foil mast QR code sticker	26 JUL 2024 17:26	Hey, my qr code felt of my foil mast again. I would like to please get it replaced. Thanks a lot	No	See response to 87.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
87	Men's Windsurfing	BRA	Foil mast qr code sticker	26 JUL 2024 17:25	Hey, my qr code felt of my foil mast again. I would like to please get it replaced. Thanks a lot	Yes	Please bring foil mast (disconnected from the board) to the TC beach office. Foil mast should be presented in a clean and dry state. TC beach office will be open from 0900 to 1700.
86	Women's Windsurfing	FRA	Spare foil mast	26 JUL 2024 17:22	While trying to attach my spare foil mast to my board (board serial number ST24IQFOC95B24010032 and QR Code SC536570 // Foil Mast serial number OMA95081231223 and QR code SC434159) to check compatibility, I realized that the foil box is not ajusted and I can't insert it and fixed it. So this manipulation is not possible in the case that my #1 foil mast breaks during a day of racing and I have to change by my spare foil mast. I ask the supplier to sand the top of the foil mast to fit the size of the foil box of the board.	Yes	Please bring the spare foil mast to the supplier along with the board. The spare foil mast is permitted to be sanded by the supplier to ensure a fit with the board. The foil mast does not need to be seen by the TC once repaired.
85	Women's Windsurfing	MEX	Boom	26 JUL 2024 17:09	Dear Technical Commitee, The clamp of my boom is loose while sailing. I would like to ask for a repair for it. The boom is supplied equipment. Thank you	Yes	Approved. Please take the boom to supplier to be repaired. The boom does not need to be seen by the TC after the repair.
84	Men's Skiff	BRA	Daggerboard	26 JUL 2024 16:50	We need to do a little repair on the trailing edge of our daggerboard. It is around 5mm length and we have a picture of it.	No	See response 83
83	Men's Skiff	BRA	Daggerboard	26 JUL 2024 16:49	We need to do a little repair on the trailing edge of our daggerboard. It is around 5mm length and we have a picture of it.	Yes	Repairs to daggerboard is approved to the extent permitted by Class Rule C.8.1(d). Foil to be presented for re-inspection by the Technical Committee in the boat park before 1700 on 27/07/2024



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
82	Women's Windsurfing	EST	Front wing & fuselage	26 JUL 2024 16:30	My front wing is dropping too low at the front of my fuse due to some material coming off and there is now a large gap causing the fuse to whistle extremely loud while I am sailing. It's not only affecting the performance of the foil, but the the whistle noise is almost defining to my ear and exceptionally disturbing. I would like the front wing to have some filler added to push it up and close the gap causing this issue or try the spare fuse to see if it fits better. I have photos to show.	Yes	Damage seen by TC - TC noted that the front wing is damaged on the rear edge of the port side wing. Repair approved by supplier. TC to see front wing after repair before returning to athlete.
81	Men's Skiff	BEL	Corrector weights	26 JUL 2024 15:51	We have been training todqay and due to heat, the tape on the corrector weight is partially melted, therefore the TC's signature is not clearly visible anymore. We request to fix the corrector weights again and the new tape to be validated/signed by the Technical Committee.	Yes	Please present required corrector weights for re-weighing and inspection at the Technical Committee Office before 1700 on 27/07/2024. UPDATE - 27/07: Corrector weights have been re-weighed and re-signed by the TC. BEL to fix corrector weights to the boat in accordance with CR C.7.4.
80	Women's Windsurfing	NZL	IQ Foil	26 JUL 2024 13:54	Sorry, our bolts we want to use are hex head, missed out this in my request. Sorry	No	See response to 79.
79	Women's Windsurfing	NZL	IQ Foil foil system bolt	26 JUL 2024 14:52	IQ foil class rule C8.1(a) allows the athlete to supply their own foil system fitting bolts. Notice #9 requires the use of supplied washers, but allows use of our own bolts that comply with C8.1(a). ER 7.1.7 also allows this. Could you confirm that we can use our own bolts which have a head rather than the torx head bolt supplied. We asked the measured for confirmation , but were told to submit a request. Many thanks	Yes	The request to replace the bolts provided by the supplier with bolts of the same size supplied by the athlete is approved. The head of the bolt is not required to have the same contour or use the same screwdriver tip as those supplied. Please note that this portal is to request repairs and replacements, not to clarify rules. For class rule questions please use the RFI system.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
78	Women's Windsurfing	FRA	Board	26 JUL 2024 14:29	While trying to attach my spare foil mast to my board (serial number ST24IQFOC95B24010032 and QR Code SC536570) to check compatibility, I realized that the foil box is not ajusted and I can't insert it and fixed it. So this manipulation is not possible in the case that my #1 foil mast breaks during a day of racing and I have to change by my spare foil mast. I ask to change the board with another one.	No	Please bring the board and both the race and the spare foil masts to the TC beach office. TC beach office closes at 1700h @@ UPDATED @@ Friday 26th July @ 1755 Board and foil have been seen. Board will not be replaced.
77	Mixed Multihull	BEL	Hull Nations branding	26 JUL 2024 13:20	The lettere B on the port side of the Nacra hull has been slightly damaged. Request to replace the letter B by a new one.	Not decided	
76	Women's Dinghy	BEL	Boom	26 JUL 2024 13:17	In removing the boom sticker as requested by Notice 14 published by the TC, the sticker leaves residue that needs to be removed. Asking for persmission to use acetone to remove residue / for the OA to remove the residue.	Yes	Permission granted to use acetone to remove residue.
75	Men's Windsurfing	DEN	Uphaul system to the rig	26 JUL 2024 14:25	I would like to request attaching an uphaul system to the rig which is made with an elastic rope attached to the batten inside the sleeve running down to the downhaul pullies and up to the boom head. Purpose with the system is to keep the uphaul rope tight and prevent it from hanging loose	No	Please note this portal is intended to address requests for repairs and replacements. For questions regarding class rules please use the RFI system.
74	Men's Windsurfing	DEN	M6 65mm and 70mm bolts	26 JUL 2024 13:27	I would like to use my own M6 65mm and 70mm bolts for connecting the foil to the board. They have same length as what we have been supplied but with a different head allowing me to use a different tool.	Yes	Approved. Class Rule C.8.1(b) stipulates that the size of the bolts and washers must be the same as supplied. The head of the bolt is not required to have the same contour or use the same screwdriver tip as those supplied.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
73	Men's Skiff	CRO	Rudder blade	26 JUL 2024 12:01	Kind request for a small (2cm) repair of the rudder blade. I would like to use a soft kit and than sand it afterwards. Thank you	Yes	Repair to rudder blade permitted. To be re-inspected at the CRO area of the boat park by the Technical Committee at 1100 on 27/07/2024. UPDATE - 27/07: Repair has been inspected by the TC.
72	Men's Windsurfing	USA	IQ Boom	26 JUL 2024 14:07	The boom head of our boom is loose, this is creating a poor connection. Please can we request to shim the carbon on the boom to make a proper fit with the boom head.	Yes	Approved to be repaired by the supplier inside the boat park. Please take the boom to the supplier to be repaired. The boom does not need to be seen by the TC after the repair.
71	Women's Windsurfing	USA	IQ Boom	26 JUL 2024 14:40	The boom head of our boom is loose, this is creating a poor connection. Please can we request to shim the carbon on the boom to make a proper fit with the boom head.	Yes	Approved. Please take the boom to supplier to be repaired. The boom does not need to be seen by the TC after the repair.
70	Women's Skiff	ITA	Mainsail	26 JUL 2024 11:31	Hi, I would like to request to repair the top of the luff of the mainsail. It has slightly come undone and I would like to stitch it up for safety.	Yes	Please present the sail for inspection of damage before repair is undertaken, before 12.00 on the 27/07 at the boat allocated place. Update - 27/07: The sail has been inspected and is approved for repair in the boat park. No further inspection required.
69	Women's Windsurfing	NED	Report of loss batten tensioner	26 JUL 2024 11:13	Batten tensioner 1 and 2 fell out and got lost - this concerns #3 sail that has already been returned to supplier. QR CODE SC4984800 and SERIAL NUMBER IKP O08368.	Yes	As this concerns a sail that has been returned to the supplier, this information will be passed to the supplier for their records.
68	Men's Skiff	FRA	Daggerboard & Rudder	26 JUL 2024 11:10	Hello, I have a repair with gel coat to do on rudder and daggerboard and to clean and polish it. Can we do it to the containers or under the white shelter on boat park ? Thanks	Yes	Foils have been inspected and repairs to daggerboard and rudder blade is approved to the extent permitted by Class Rule C.8.1(d). The foils may be removed from the boat park to the container to facilitate this repair. Foils to be presented for re-inspection by the Technical Committee in the boat park before 1700 on 27/07/2024



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
67	Women's Windsurfing	NED	Boom head repair	26 JUL 2024 11:07	Request to repair: asking for a permission to repair the boom head connection. There is space/backlash on the boomhead, therefore head is loose QR CODE : SC007850 Serialna SVT 055 24923.	Yes	Approved. Please take the boom to supplier to be repaired. The boom does not need to be seen by the TC after the repair.
66	Women's Skiff	CAN	'Look of the Games' mainsail sticker - misspelled name	26 JUL 2024 10:42	The last name of my crew was spelt wrong on our mainsail. We ask for a new sticker with the correct spelling. The name should be changed from 'LAFRANCE' to 'LEWIN LAFRANCE' (same last name as skipper).	Yes	Approved to bring the sail to Grape Fruit office in building one to change the branding by the supplier.
65	Men's Dinghy	EST	Rudder and Centreboard	26 JUL 2024 9:43	Can the supplier please sand the trailing edge of the supplied foils as there are a lot of vibrations and humming noises starting at winds around 10kt?	Yes	Approved to be fixed by the supplier
64	Women's Dinghy	CHN	Boom	26 JUL 2024 9:15	Dear Sir, there's trace of damage at the front part of the boom, and the brand of the boom is not E6 as the cleat doesn't match to what I applied before. I apply for changing.	Yes	Please bring the boom to the supplier are at 10.30 to be inspected by the TC. UPDATE: 26/07/2024: TC inspect the boom and approves to be changed by the supplier, no need to be re-inspected. Old serial number: BM103264427 New serial number: BM103264453
63	Men's Dinghy	DEN	Rudder gudgeon	25 JUL 2024 21:54	I would like to request a substitution of the rudder gudgeons as they are too loose for the rudder head pins	Yes	Rudder gudgeon inspected by the TC and has been approved to be replaced by the supplier. No need to be re-inspected after the replacement
62	Men's Dinghy	DEN	Rudder Gudgeons	25 JUL 2024 17:16	The pins of the rudder head are loose in the gudgeons	No	Please request either a repair or replacement
61	Women's Windsurfing	NED	Boom maintenance	25 JUL 2024 16:57	Question to TC: Can I get permission to use super glue on the bolts of the boom to avoid the bolts from falling out?	No	This action is not permitted by the competitor. Please bring boom to TC for review. TC beach office is open from 0900 and closes at 1700 so bring equipment between these times.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
60	Men's Dinghy	ITA	Tiller	25 JUL 2024 16:57	May I please take my Tiller of ILCA ITA Men to have maintenance work done to it from the boat park to the container? Once finished back to the Boat. Many thanks. Lorenzo	Yes	Please bring the tiller to the TC office to day for inspection 25/07/24 17:35 hrs.TC inspect the item and approved to take it to the boat park for repair. No need to be re-inspected
59	Men's Skiff	AUS	Spinnaker	25 JUL 2024 16:44	Request to take sail to have hole in spinnaker repaired. Hole is 2m up from the clew and 1m in from the leach.	Yes	TC inspect the sail and approved to take out of the boat park for repair. Sail must be re-inspected by the TC prior to the first race
58	Women's Windsurfing	NED	Rearwing	25 JUL 2024 16:36	I am making a request for repair of the rear wing. Rear wing with QR CODE SC572 816 and SERIAL NUMBER: 143231128 During a training session I hit an anchor which was in the water. This caused damage on the leading edge of the rear wing. I would like to request a repair.	Yes	Damage to rear wing seen by TC. Damage is genuine. Repair approved by supplier and does not need to be seen by TC once completed.
57	Women's Windsurfing	NED	Boom	25 JUL 2024 16:33	Replacement of boom QR SC 006 342 and serial nr SVT 05442717 because of damage to the boom.	Yes	Approved. The replacement of the boom is permitted. Please bring old boom to TC beach office and then collect new boom from supplier. New boom shall be presented to TC for checking once collected from supplier.
56	Women's Windsurfing	ISR	Foil mast repair	25 JUL 2024 14:27	My mast have two problems I would like to solve, 1. Scratch in the upper part near the fuselage 2. the mast head is not fitting into the mast base as it should and needs to be sanded to be in the recommended manufacturer angle	Yes	Please bring board and mast foil to TC for review. TC office at the beach closes at 1700 so bring prior to this time. @@ UPDATED @@ Thursday 25th July 1710 Scratch on foil mast seen by TC. Damage is genuine. Repair by supplier is approved and does not need to be re-seen by TC. Foil mast head has been withdrawn by competitor but may be opened up at a later date.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
55	Men's Windsurfing	SUI	Boom QR 675406	25 JUL 2024 13:38	Permission for a repair of the screw connecting the outhaul pulley to the boom clew. It's coming out and high risk of loosing it with additional dysfunction of the outhaul system as a consequence.	Yes	Damage seen by TC and is genuine. Please take boom to supplier for repair to outhaul system screws and captive nut on the outboard end of the boom. The repair does not need to be seen by the TC once completed.
54	Women's Windsurfing	GBR	Back end boom clips	25 JUL 2024 13:17	The boom clip adjusters are prone to getting undone by the outhaul system and also popping off. Please can I have permission to use tape or rubber type Bands to keep them secured in place to Prevent damage to the book or loss of the clips.	Yes	This action is not permitted by the competitor. Please bring the boom to the TC office for review. TC office at the beach closes at 1700 so bring prior to this time. @@ UPDATED @@ Friday 26th July @ 0936 Damage seen by TC and is genuine. Repair approved by supplier. TC does not need to see boom after repair.
53	Women's Windsurfing	GBR	Boom Back end screws	25 JUL 2024 13:14	Whilst sailing the screws on the back end of the boom are working loose and close to falling out. They have already fallen out in the boat park. Please can I have permission to use lock tight/superglue on the screws and tape over the top to keep them secured in the boom please?	No	This action is not permitted by the competitor. Please bring boom to the TC for review. TC office at the beach closes at 1700 so bring prior to this time.
52	Men's Windsurfing	FRA	USE Front Wing	25 JUL 2024 11:40	Tiny coating bubbles have appeared in various spots on the wing. It needs a maintenance work to get it back to original specs	No	Maintenance by the competitor is not permitted. Please take front wing to TC at the beach TC office to review potential damage with TC and supplier. TC office will close at 1700 so bring the equipment prior to this time.
51	Men's Skiff	DEN	Hull	25 JUL 2024 9:12	From the production of the boat where they put gelcoat is put on the transom. This has been done badly and lips below the water line. We would like to make this flush; not changing any shape just removing excess gel coat.	Yes	
50	Men's Dinghy	FIJ	Hull	25 JUL 2024 8:40	Small repair required front port side gunnel	Yes	approved to be repair by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposeonse
49	Men's Windsurfing	SUI	Boom	24 JUL 2024 20:29	The tail of the boom (the clew) especially the screws that hold the pulley for the outhaul system are not glued. Each time I use the boom there is some risks to lose the screws. Boom qr code: 675406	No Class rules allow maintenance. The ERS excludes bonding from its definition of maintenance. Therefore, use of glue is not permitted.
48	Men's Windsurfing	GBR	Front wing Sc 441331	24 JUL 2024 19:57	Sc 441331 QR code has fallen off, request for replacement	Yes Please bring the front wing to the TC office at the beach this morning, 25 July 2024.
47	Men's Windsurfing	DEN	Boom: SC 040 200	24 JUL 2024 19:48	My boom is slippery after sailing in dirty water 2 days ago. I tried to clean it but the only effective way is to make it wet and scrape out the grease with a blade from a hacksaw. Please confirm if I am allowed to do this.	No The action of scraping with a blade will damage the covering on the supplied equipment and is not allowed by the supplied equipment guidelines.
46	Men's Windsurfing	BRA	Foil Mast QR code sticker	24 JUL 2024 18:36	Hey, my qr code sticker felt of my racing mast again, I would please like to get it replaced. Thanks a lot	Yes Please come to the Windsurfing inspection area with the item on 25 July at 10.30
45	Men's Windsurfing	POL	IQFOIL POL M Board repair	24 JUL 2024 17:04	I need to request the repair of the foil box in my board due to manufacturer defect. Foilbox is too small and the foil mast does not fit in properly. Iqfoil technical crew will take care of this issue.	Yes 24/07/2024: Please bring the board to Windsurfing inspection area on 25 July at 10.00am 25/07/2024: Following inspection the request is approved for repair by the supplier inside the boat park.
44	Women's Skiff	POL	Mast track	24 JUL 2024 16:50	During sailing our mast track broke and we need to replace the broken piece with a new one. We ask for a permission to do so. Kind regards	Yes Approved- no need for re-inspection



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
43	Women's Skiff	POL	Mainsail	24 JUL 2024 16:45	During sailing our bolt rope in front of the mainsail next to the fourth batten has ripped. We need to take the mainsail to the sail master a repair it. We ask for a permission to do so. Kind regards	Yes	Approved to take out from the Boat Park Sail need to be re-inspected before the first race
42	Women's Windsurfing	PER	Boom	24 JUL 2024 16:30	The head of the boom stays loose when the rope is full tightened to the mast. We request a repair of the boom to make it stiffer to avoid any movement when it's closed.	Yes	The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
41	Women's Windsurfing	ITA	FOIL MAST - QR CODE SC 207 890	24 JUL 2024 16:25	Trailing edge is damaged, I kindly ask for repair	Yes	
40	Men's Windsurfing	DEN	Boom: SC 040 200	24 JUL 2024 16:06	The boom head does not attach tightly to the to the boom and therefore moves a lot when pumping. We would like to add tape on the inside where the head attaches to create a tighter fit and prevent it from moving to also secure no plastic parts breaking.	Yes	The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
39	Men's Windsurfing	JPN	iQFOiL Men Boom qr code:	24 JUL 2024 15:26	The attachment of the boom to the mast is not tight enough and move easily. Can I repair it?	Yes	The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
38	Women's Windsurfing	CRO	Board	24 JUL 2024 15:15	Please approve board change that was broken afloat today	Yes	Item inspected by the TC and approved to be changed by the supplier. New board needs to be presented to the TC at the Windsurfing inspection area on the 25 July at 10.00 am
37	Men's Windsurfing	CHN	Front wing's sticker	24 JUL 2024 14:44	The new sticker with its serial number SC 736005 on the front wing peeled off again after training for about two hours. We apply for a new sticker on, please.	Yes	Approved New QR code: SC 578137



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
36	Women's Windsurfing	NOR	Front wing: QR: SC 249 422, SR: FW900068231122	24 JUL 2024 14:20	I would like to report a damage on the front wing, damaged in the tip of the front wing.	Yes	Item inspected by the TC and approved to be repair by the supplier. No further inspection needed
35	Women's Skiff	SWE	Rudder pin	24 JUL 2024 13:43	Requesting to replace the rudder pin because of damage that makes the rudder wobble.	Yes	Approved to be replaced
34	Women's Windsurfing	NED	iQfoil W NED	24 JUL 2024 13:41	1. Request to repair rear wing QR CODE SC572 816 - SERIAL NUMBER: 143231128 During a training session I hit an anchor that was in the water. This caused damage to the leading edge of the rear wing. I would like to request a repair. ----- 2. Report of loss of batten tensioners 1 and 2 Sail QR CODE SC4984800 - SERIAL NUMBER IKP O08368. Batten tensioners 1 and 2 fell out and were lost. ----- 3. Request for repair / permission for maintenance gear work - Can I get permission to put (transparent) tape on the boom head connection because of space/backlash? - Can I get permission to scrape the grip of the boom? - Can I get permission to use super glue on the bolts of the boom to avoid the bolts from falling out? The above was also submitted as RFI yesterday.	No	Please send request one by one to be able to reply
33	Men's Dinghy	IVB	ILCA7 Battens	24 JUL 2024 13:23	Battens received are bent, when and where can they be replaced please?	Yes	Please refers to notice 25



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
32	Women's Windsurfing	NED	Foilmast sticker iQfoil W NED	24 JUL 2024 13:06	I received a new QR sticker during stage 1 on 22 July - on my foilmast with QR CODE SC 785 815 and serial nr OMA95 225 240120. The sticker got lost during training the next day. I would like to request a new QR sticker.	Yes	Please present equipment to TC in a dry and clean condition to get a replacement sticker New sticker applied. New QR code : SC 765211
31	Men's Windsurfing	ARU	Boom	24 JUL 2024 10:43	We would like to request a reinforcement of the boom head because it has started to feel loose around the mast.	Yes	The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
30	Women's Windsurfing	CRO	Helmet approval	24 JUL 2024 10:28	Please approve my self painted helmet that passed equipment inspection.	No	Please refer to the Windsurfing ITO
29	Men's Skiff	CRO	Gantry repair and laser alignment test with the rudder blade in a dark place	23 JUL 2024 21:12	At todays training we suffered damage to our gantry. It needs repair and laser alignment test with rudder blade in a dark place. We kindly ask if we can have suitable dark place for the intervention or permission to arrange it on our own in our container.	Yes	In accordance with RE 3.1. Repairs and replacements of equipment made after completion of prevent equipment inspection shall require prior written approval of TC. Prior to pre-event equipment inspection routine maintenance and repairs may be carried out provided such repairs are made in such a way that the essential shape characteristic and function of the original are affected. Allowed to take the rudder out of the boat park to be repaired in the container park.
28	Men's Windsurfing	FRA	« USE » front wing	23 JUL 2024 18:55	Little scratch on the leading edge of the use front wing, would need a repair.	Yes	Equipment to be repaired by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
27	Men's Skiff	AUT	Centreboard	23 JUL 2024 18:38	Today while training we hit a drifting object in the water. Now, when preparing the boat for tomorrows measurement we saw that due to this hit the centreboard has a small damage on the leading edge and a small scratch on the side. We ask permission to repair these 2 issues. As we would need to use some gelcoat for the repair we also request to bring the centreboard for the time of the repair out of the boatpark, to our Container, where we have a proper environment to do the repair.	Yes	In accordance with RE 3.1. Repairs and replacements of equipment made after completion of prevent equipment inspection shall require prior written approval of TC. Prior to pre-event equipment inspection routine maintenance and repairs may be carried out provided such repairs are made in such a way that the essential shape characteristic and function of the original are affected. Allowed to take the daggerboard out of the boat park to be repaired in the container park.
26	Women's Windsurfing	GBR	IQ Foil board 95	23 JUL 2024 17:54	After taking the board to be repaired the manufacturer and repairer said it is beyond repair we would like the request to replace please	Yes	Equipment was inspected by the TC and approved to be replace by the supplier new board serial number: xx0038 QR code:152549
25	Women's Skiff	DEN	Fx centerboard and rudder	23 JUL 2024 16:51	I request repairing our foils as there are some damage to it. I have had 49er technical officers to look at it. Peter Hansen	Yes	In accordance with RE 3.1. Repairs and replacements of equipment made after completion of prevent equipment inspection shall require prior written approval of TC. Prior to pre-event equipment inspection routine maintenance and repairs may be carried out provided such repairs are made in such a way that the essential shape characteristic and function of the original are affected. Allowed to take the foils out of the boat park to be repaired in the container park.
24	Women's Windsurfing	EST	Iqfoil board	23 JUL 2024 16:40	I request to fix the front of my board.	Yes	equipment approved to be repair by the supplier
23	Women's Windsurfing	ESP	Front wing	23 JUL 2024 16:21	I had a crash this morning with a buoy and I have some scratches at the front of the port leading edge. I would like to get it repaired.	Yes	Equipment allowed to be repair by the supplier
22	Women's Windsurfing	ESP	Board	23 JUL 2024 16:18	I request to repair my board, I had a catapult this morning and I have a crash on my nose that fills water.	Yes	Equipment allowed to be repair by the supplier



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposonse
21	Men's Windsurfing	DEN	Plastic cap for mini Tuttle	23 JUL 2024 16:06	The plastic cap for mini Tuttle does not make a tight fit, and I therefore request to get a new one because it is important for durability and performance	Yes Equipment approved to be replace by the supplier
20	Women's Skiff	ITA	Rudder	23 JUL 2024 15:34	Hello, I would like to repair my rudder, it's a small damage at the end of the exit profile. Jana Germani	Yes In accordance with RE 3.1. Repairs and replacements of equipment made after completion of prevent equipment inspection shall require prior written approval of TC. Prior to pre-event equipment inspection routine maintenance and repairs may be carried out provided such repairs are made in such a way that the essential shape characteristic and function of the original are affected.
19	Men's Windsurfing	BRA	Boom head	23 JUL 2024 14:22	Our boom head is not holding its position on the boom. We would like to have it repaired. We also welcome any solution or replacement, but we believe that adding some mylar film between the boom head and the boom would solve the issue. Thank you!	Yes The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
18	Women's Windsurfing	FRA	IQfoil Fuselage : QR Code : SC 446 890 / serial number : 155 24 01 26	23 JUL 2024 13:16	This fuselage had damages before stage one of mesurement. The repair request was accepted. The main part of damages had been repared already by the supplier. But it remains a part to be repaired. We ask the supplier to finish the repair.	Yes Please bring the fuselage to the TC at the inspection area at the beach on 24 July at 8:45 24/07 The item was inspected and approved to be repair by the supplier. No further inspection needed.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
17	Men's Windsurfing	GRE	Changing number of Spare sail	23 JUL 2024 13:12	Hello, By mistake i registered the wrong QR Code for the spare sail. I want to change the number of the spare sail. The wrong number we registered is SC 2787985 (we already gave back this sail to the supplier yesterday 22/7). The new QR code of the correct sail is SC 4705013 Thank you Best regards Vyron Kokkalanis	Yes	Approve input data correction on spare sail: The new QR code of the correct sail is SC 4705013
16	Women's Windsurfing	FRA	IQfoil Board number : QR : SC 536 570 serial number ending : 24010032	23 JUL 2024 13:11	The board supplied (identified QR SC 536 570) was weighted at measurement's second stage (this morning) at 11.410Kg. It is above the tolerances of the supplier, and more than 300grammes above the minimum of the class rules tolerances. This board was new (1 training), totally dry. It means the board went out from the factory already out of tolerances, despite monotype policies. Never in the last 4 years we received a new board so heavy. We ask to change the board to have one with a weight similar as the one used by other competitors.	No	The board complies with the Class Rules
15	Women's Windsurfing	GBR	IQ Foil Board	23 JUL 2024 12:51	After sailing yesterday the area of the front fin/foil box has dented and recessed so we are unable to get a solid connection in the foil box, we request to replace or repair the board	No	See answer on request 26
14	Women's Dinghy	ITA	sticker on the boom	23 JUL 2024 11:10	the sticker of the event on my boom has been stuck upside down	Yes	Please refer to notice 14



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposeonse
13	Men's Windsurfing	GRE	GRE Iq Foil Coach Boat	22 JUL 2024 21:35	Hello, Due to some technical reasons we were not able to bring our Iq Foil Coach boat earlier in the Olympic Marina, we are now able to bring the boat, our stickers are already on (number 101), engine cover is on and VSR letters hidden. And we pass the security control tomorrow morning at 9:00 Thank you for your understanding Best regards, Georges SKLAVOUNOS Team Leader of Greece	No Please complete a RFI for this question. This form it is only for Equipment repair and replacement request.
12	Women's Windsurfing	HKG	Boom	22 JUL 2024 18:22	iQFOiL Women HKG Dear Technical committee, Since the clamp of the boom that connects the boom to the mast is loose and we believe it affects the stability and functionality of the boom. We would like to seek your kind permission to repair or replace, depending on your assessment. If possible, we would like to arrange a time slot for the item to be checked, at you earliest convenience. The boom is supplied equipment. Thanks for your assistance and consideration. iQFOiL HKG Ma Kwan Ching	Yes The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved Reposeonse
11	Men's Windsurfing	FRA	« USE » front wing	22 JUL 2024 18:20	Little scratch on the leading edge of the front wing. I request for a repair.	No
10	Men's Windsurfing	HKG	Boom	22 JUL 2024 18:15	iQFOiL Men HKG Dear Technical committee, the clamp of the boom that connects the boom to the mast is loose and we believe it affects the stability and functionality of the boom. The boom is supplied equipment. We would like to ask permission either to repair it or replace, depending on your assessment. We would like to arrange for the item to be checked at you earliest convenience. Thanks for your assistance iQFOiL HKG	Yes The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
9	Women's Windsurfing	CRO	Board change	22 JUL 2024 18:09	My name is Palma Cargo from Croatia, iq foil windsurfing. I request to change my board; serial number: St24iqfoc95b24010017 SC389976. The reason is that i cannot put my foil mast in the box to the end of the box and then i can't make angle between fuselage and the board more than 0.8	Yes Equipment approved to be replace by the supplier: new serial number: xx0047 QR code: 305267
8	Men's Windsurfing	BRA	Foil mast - serial number OMA 216 240109	22 JUL 2024 17:59	I got the QR code replaced 2 days ago and today after sailing it felt of again. I would need to get another qr code into the foil mast. Thanks a lot	Yes Equipment replaced by the supplier New QR code: sc565028



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
7	Women's Windsurfing	GER	Foil Mast	22 JUL 2024 17:46	There is a small dent on the trailing edge of the foil mast approx. 5cm down from the upper end of the foil	Yes	23/07/2024: Please bring the equipment to the TC at the inspection area on the beach on 24 July before noon. 24/07/2024: Item has been inspected by the TC and repair by the supplier has been accepted. There is no need for a re-inspection after the repair.
6	Men's Dinghy	NOR	Gelcoat cavity in cockpit floor	22 JUL 2024 17:46	My boat had an air bubble underneath the gel coat in the cockpit. The gel coat fell of and I am asking for permission for Ferdi to fix it.	Yes	Equipment has been inspected Repair by the supplier allowed- no need to be re-inspection
5	Women's Windsurfing	EST	Boom head	22 JUL 2024 16:04	My boom head is very loose and wobbles while I am sailing and pumping, I would like to open the boom head to try and adjust it to fit tightly around the boom head tube.	Yes	The boom as supplied is designed to grip the mast firmly. If the boom head no longer does this then it would need to be repaired by the supplier. A repair by the supplier is approved in this case.
4	Women's Dinghy	BEL	Branding on boom - ILCA 6	22 JUL 2024 15:39	The branding on the clew end of the boom is interfering with the movement of the clew tiedown resulting in its sticking as it is eased. Normally in these situations we would lubricate the clew tiedown and boom, but we are prohibited in doing so. Can the branding be moved forward?	Yes	Please refer to notice 14
3	Women's Windsurfing	EST	Iqfoil board	22 JUL 2024 15:31	I have a damaged crack on the front of the board from a crash which is taking in water. I need this repaired to stop water going in the board.	Yes	Equipment approved to be repair by the supplier.
2	Men's Dinghy	FRA	Centerboard	22 JUL 2024 14:51	When my manager pick up my boat he signalled my centreboard was bent. I ask replacement of my centreboard. Thanks	Yes	Equipment has been presented for inspection. Damage confirm and replaced by supplied allowed



Equipment repair/substitution summary

As of THU 8 AUG 2024 at 19:43

Request Number	Event	Sail Number	Equipment	Date/Time	Request	Approved	Reposonse
1	Men's Dinghy	KOR	Safety lock for rudder	22 JUL 2024 0:10	This lock is to low and needs to be moved up. It is not possible to remove the rudder . Since we want to launch on July 22nd at 12:30 it needs to be done before that time. The athlete will be there from 11:15 hours.	Yes	Equipment to be inspected by the TC at the supplier area. Update: 26/07/2024 at 11.00 am. Equipment inspected by the TC and approved to be repair by the supplier. No need to be re-inspected